

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION.
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test <u>9-(2-08</u>	3 Operator: Elm	Ridge Exp	oloration CO LLC	API #30-039- <u> </u>	921
Property Name Ring	on 19 Wel	No. 3	Location: Unit_Z	Section 19 Towns	ship AN Range Low
Well Status (Shut-In or	Producing) Tub	oing 45	Intermediate Cas	sing 48 Braden	head <u>Ø</u>
OPEN BRADENHEA	D AND INTERME	DIATE TO	ATMOSPHERE INDI	VIDUALLY FOR 1	5 MINUTES EACH
	PRESSURES: INTERMEDIATE	CASING	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothir	ıg	
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			_ Gas & Water		
			Water		
If bradenhead flowed water	r, check all of the de	scriptions t	that apply below:	(2)	232425262>3
CLEARFI	RESHSAL	TY	SULFURBLACI		
5 MINUTE SHUT-IN BI	RADENHEAD		INTERMEDIATE	011	RECEIVED 3311 CONS. DIV. DIST 3 7012
		<del></del>			STITOI 88 P.
		<u>,</u>	·		
·			<del></del>		
By Oscary Persegre			Witness		
Pumper Osces (Position)	in Kenjeyru	<u> </u>			
É-mail address	· · · · · · · · · · · · · · · · · · ·				