

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 2/7/08 Operator: Elm Ridge Explo	oration CO LLC API #30-043-20	539_
Property Name On Ca Well No. 3	Location: Unit I Section P Towns	hip 23 Range 04
Well Status (Shut-In or Producing) Tubing 20 Ir	ntermediate <u>NA</u> Casing <u>NA</u> Bradenh	ead NA
OPEN BRADENHEAD AND INTERMEDIATE TO	ATMOSPHERE INDIVIDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow	i
10 minutes	Surges	l .
15 minutes	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions th	nat apply below:	RECEIVED 33 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
CLEARFRESHSALTY	SULFUR BLACK	-05/15/
S MANUTE CHAIR IN DO ADENIUS AD AAA	DITEDITEDIATE NA	FFB 2008
5 MINUTE SHUT-IN BRADENHEAD MA	INTERMEDIATE ///A	, DIV. DIST. 3 N
REMARKS:	100	E11101681
Slim hole well - cement to s	urface. No bradenhead	
ву <b>С.</b> С. В.	Witness	
Pumper		/
(Position)	7" -	70 112' To 2516'
E-mail address	20813	10 0010