

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/7/08 Operator: Elm Ridge Ex	cploration CO LLC API #30-043-20735
Property Name Matin Whi Hakwell No. 5	4 Location: Unit Section 34 Township 23 Range 4
Well Status (Shut-In or Producing) Tubing 20	Intermediate MA Casing 32 Bradenhead O
OPEN BRADENHEAD AND INTERMEDIATE T	TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges
15 minutes	Down to Nothing
20 minutes	Nothing
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN BRADENHEAD O	Sthat apply below: SULFUR BLACK INTERMEDIATE NA SULFUR BLACK PRECEIVED SULFUR SULFUR SULFUR BLACK SULFUR BL
REMARKS:	Didition and was
	£110198F2
By All	Witness
Pumper	
(Position)	,
E-mail address	