

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

- · · · · ·

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/7/08	Operator	BMG	_API #30-0_39	-06769
Property Name <i>FRMU</i> Well	l No. 9	_Location: Unit <u>#</u>	Section <u></u> 36	hip <i>271</i> / Range <i>/ E</i>
Well Status (Shut-In or <u>Producing</u>) Tubing 30 Intermediate MR Casing 30 Bradenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES TIME BRADENHEAD INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes O		Steady Flow		
10 minutes \mathcal{O}		Surges		
15 minutes O		Down to Nothi	ng	
20 minutes		Nothing	X	
25 minutes		Gas		
30 minutes		Gas & Water_		
		Water	,	
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEARFRESHSAI		SULFUR BLAC	K	2324 252627283
5 MINUTE SHUT-IN BRADENHEAD CREMARKS	<u></u>	INTERMEDIATE	118192027	RECEIVED 12 CONS. DIV. DIST. 9
· ·			1,0	L CONS. DIV. DIST 3 6
	<u> </u>		Y BI	351110168103
By Ban I Horfole		Witness		
(Position)				
E-mail address				