



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

ELM Ridge Exploration

Date of Test 2-26-08 Operator CO LLC API #30-043-20841

Property Name Lybrook South Well No. 15 Location: Unit A Section 19 Township 23^N Range 6^W

Well Status (Shut-In or Producing) Tubing NA Intermediate NA Casing 125 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>125</u>	Steady Flow	
10 minutes	<u>0</u>		<u>125</u>	Surges	
15 minutes	<u>0</u>		<u>125</u>	Down to Nothing <input checked="" type="checkbox"/>	
20 minutes	<u>0</u>		<u>125</u>	Nothing	
25 minutes	<u>0</u>		<u>125</u>	Gas <input checked="" type="checkbox"/>	
30 minutes	<u>0</u>		<u>125</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

Bradenhead - Pressure will Not Register on gauge - Opened
valve - puff of gas down to nothing.

By Joe J. Kovata, Jr.
Pumper.
(Position)

Witness _____

E-mail address _____

