



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Elm Ridge Exploration

Date of Test 2-27-08 Operator CO LLC API #30-039-24451

Property Name Rincon Well No. 10 Location: Unit G Section 13 Township 23^N Range 7W

Well Status (Shut-In or Producing) Tubing NA Intermediate NA Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>60</u>	Steady Flow	
10 minutes	<u>0</u>		<u>60</u>	Surges	
15 minutes	<u>0</u>		<u>60</u>	Down to Nothing <u>✓</u>	
20 minutes	<u>0</u>		<u>60</u>	Nothing	
25 minutes	<u>0</u>		<u>60</u>	Gas <u>✓</u>	
30 minutes	<u>0</u>		<u>60</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Bradenhead Pressure Not enough to register on gauge -
Opened valve - puff of gas - down to nothing.

By J. J. Lopez

Witness

Pumper
(Position)

E-mail address

