



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

*Elm Ridge Exploration*

Date of Test 2-21-08 Operator CO LLC API #30-039-24573

Property Name State 16 Well No. 3 Location: Unit 4 Section 16 Township 23 Range 6

Well Status (Shut-In or Producing) Tubing 68 Intermediate NA Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>90</u>	Steady Flow	
10 minutes	<u>0</u>		<u>90</u>	Surges	
15 minutes	<u>0</u>		<u>90</u>	Down to Nothing <u>✓</u>	
20 minutes	<u>0</u>		<u>90</u>	Nothing	
25 minutes	<u>0</u>		<u>90</u>	Gas	
30 minutes	<u>0</u>		<u>90</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Bradenhead = Puff of GAS when valve was opened to Atmosphere.  
Not enough pressure to register on gauge.

By Joe J. Lomonte Jr.  
Pumper  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_

