



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-7-08 Operator: Elm Ridge Exploration CO LLC API #30-0 39-08147
Property Name Sicasila L140 Well No. 1 Location: Unit B Section 15 Township 23 Range 2
Well Status (Shut-In or Producing) Tubing 22 Intermediate N/A Casing 300 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>N/A</u>	<u>300</u>	Steady Flow	
10 minutes	<u>0</u>		<u>300</u>	Surges	
15 minutes	<u>0</u>		<u>300</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>300</u>	Nothing	
25 minutes	<u>0</u>		<u>300</u>	Gas	
30 minutes	<u>0</u>		<u>300</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:



By [Signature]
Pumper
(Position)

Witness _____

E-mail address _____