



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-12-08 Operator: Elm Ridge Exploration CO LLC API #30-0 39-21420

Property Name Jicarilla JV KD Well No. 1 Location: Unit P Section 4 Township 23 Range 3

Well Status (Shut-In or Producing) Tubing 70 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>N/A</u>	<u>0</u>	Steady Flow	
10 minutes	<u>0</u>		<u>0</u>	Surges	
15 minutes	<u>0</u>		<u>0</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>0</u>	Nothing	
25 minutes	<u>0</u>		<u>0</u>	Gas	
30 minutes	<u>0</u>		<u>0</u>	Gas & Water	
				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

PACKER IN HOLE



By Dwight W. Allen

Witness \_\_\_\_\_

Pumper  
(Position)

E-mail address \_\_\_\_\_