

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1 15 08 Operator: Elm Ridge Ex	xploration CO LLC API #30-0 39	-23014
Property Name Jicarila 41 Well No. 8	Location: Unit M Section 3 Towns	ship SRange 44
Well Status (Shut-In or Producing) Tubing 420	Intermediate Casing 420 Braden	head
OPEN BRADENHEAD AND INTERMEDIATE T	TO ATMOSPHERE INDIVIDUALLY FOR 1	5 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes <u>0</u> 420	Steady Flow	
10 minutes 0 420	Surges	
15 minutes () 420	Down to Nothing	
20 minutes	Nothing \mathcal{O}	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY	SULFURBLACK	\$ 37
CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE REMARKS: RECEIVED OF ONE CONS. DIV. DIST. 3		
	4/19/	शिका हारी प्रिंग विश्वास
Ву	Witness	<u></u>
Pumper fell Den (Position)		
E-mail address	,	