

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of	Геst <u>2-12-0</u>	♂Operator: Elm I	Ridge Expl	loration CO LLC A	.PI #30-043- <u></u>	5198
Property Name <u>JiCarilla H 163</u> Well No. 4 Location: Unit <u>C</u> Section <u>H</u> Township <u>Range</u>						
Well Status (Shut-In or Producing) Tubing 35 Intermediate Casing 20 Bradenhead 0						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	BRADENHEAD	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	0	NA	20	Steady Flow		
10 minutes	. 0		20	Surges		
15 minutes	0		20	_ Down to Nothin	g	
20 minutes	D		20	Nothing		
25 minutes	0		20	Gas		
30 minutes	0		20		· · · · · ·	
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK \$\frac{1000}{1000} \text{ BLACK}						
Water						
REMARKS:						ELSTIPLE
	7 22					
By Veldly Weld				Witness		
(P	Pumper osition)					
E-mail addr	ess					