

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of	Test <u>2-8-6</u>	Soperator: Elm F	Ridge Expl	oration CO LLC A	PI #30-043	5243
Property Name Ji Carilla N 163Well No. 4 Location: Unit Section 20 Township 3 Range 0						
			-,	ntermediate M/ Cas		
TIME		PRESSURES: INTERMEDIATE	CASING	A IMOSPHERE INDIV	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	0	N/A	0	Steady Flow		
10 minutes	0	,	0	Surges		
15 minutes	0		0	Down to Nothing	g	
20 minutes	D		0	Nothing		
25 minutes	D		0			
30 minutes	D		0	Gas & Water		-
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE N/A REMARKS: PACKER IN Hole						
SI SI DI SI						
				W-044		
By Villey Well				Witness		
	Pumper osition)					
E-mail addr	ŕ					