



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
/ FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test \_\_\_\_\_ Operator: Elm Ridge Exploration CO LLC API #30-043- 20028

Property Name Jicasilka ASS Well No. 7 Location: Unit 0 Section 26 Township 23N Range 3W

Well Status (Shut-In or Producing) Tubing 5P Intermediate \_\_\_\_\_ Casing 5P Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes <u>0</u>			<u>51</u>	Steady Flow _____	
10 minutes <u>0</u>			<u>51</u>	Surges _____	
15 minutes <u>0</u>			<u>51</u>	Down to Nothing _____	
20 minutes _____				Nothing <u>0</u> _____	
25 minutes _____				Gas _____	
30 minutes _____				Gas & Water _____	
				Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:



By \_\_\_\_\_

Witness \_\_\_\_\_

Pumper  
(Position)

*Rich Dean*

E-mail address \_\_\_\_\_