



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emurd.state.nm.us/ocd/District I%20District.htm](http://emurd.state.nm.us/ocd/District%20I%20District.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12/18/07 Operator CHURON API #30-0 3921717
Property Name R/VLOW Well No. 79A Location: Unit D Section 17 Township 27N Range 6W
Well Status(Shut-In or Producing) Tubing 118 Intermediate 132 Casing 132 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE

REMARKS:

By MAINT PLANNER
(Position)

Witness

