



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 3-6-08 Operator: Elm Ridge Exploration CO LLC API #30-039- 21382


Property Name JIC AP2 #1- Well No. 4 Location: Unit M Section 11 Township 23 Range 3

Well Status (Shut-In or Producing) Tubing 0 Intermediate N/A Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>N/A</u>	<u>35</u>
10 minutes	<u>0</u>	<u></u>	<u>35</u>
15 minutes	<u>0</u>	<u></u>	<u>35</u>
20 minutes	<u></u>	<u></u>	<u></u>
25 minutes	<u></u>	<u></u>	<u></u>
30 minutes	<u></u>	<u></u>	<u></u>

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	☒	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

dug out & plumbed up above ground.
Thanks
HW

By _____

Witness _____

Pumper
(Position)

Don Shipley

E-mail address _____