



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-18-08 Operator Elm Ridge API #30-0 39-05343
Property Name AXIPacked Well No. 2 Location: Unit 19 Section 19 Township 24 Range 4
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 54 Intermediate N/A Casing 82 Bradenhead 85

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			<u>85</u>		
10 min			<u>86</u>		
15 min			<u>87</u>		
20 min			<u>89</u>		
25 min			<u>90</u>		
30 min			<u>91</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓ Light</u>	
Surges	
Down to Nothing	<u>2000 MAR 18 '08</u>
Nothing	<u>OIL CONSV. DIV.</u>
Gas <u>✓</u>	<u>DIST. 3</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Bleed head for 38 seconds then down to a
whisper for rest of test.

By Rickard L. Jones

Witness Monica Kuchling

(Position)

E-mail address _____