#59 30-039-07537

#128 30-039 - 23777

#528 30-039- 24818

## DATA SHEET FOR DEEP GROUND BED CATHODIC PROTECTION WELLS NORTHWESTERN NEW MEXICO (Submit 3 copies to OCD Aztec Office)

Operator MERIDIAN OIL Location: Unit SW Sec. 27 Twp29 Rng 7
Name of Well/Wells or Pipeline Serviced SAN JUAN 29-7 UNIT #59, #128, #528
cps 103w
Elevation 6855' Completion Date 9/21/71 Total Depth 500' Land Type* N/A
Casing, Sizes, Types & Depths N/A
If Casing is cemented, show amounts & types used N/A
If Cement or Bentonite Plugs have been placed, show depths & amounts used
Depths & thickness of water zones with description of water when possible:
Fresh, Clear, Salty, Sulphur, Etc. 190' TO 210' REGETVE
Depths gas encountered: N/A MAY31 1991
Type & amount of coke breeze used: 8200 lbs. DIST: 3
Depths anodes placed: 440', 430', 395', 385', 375', 365', 355', 345', 335', 325'
Depths vent pipes placed: N/A
Vent pipe perforations: 325'
Remarks: gb #2

If any of the above data is unavailable, please indicate so. Copies of all logs, including Drillers Log, Water  $\Lambda$ nalyses & Well Bore Schematics should be submitted when available. Unplugged abandoned wells are to be included

<sup>\*</sup>Land Type may be shown: F-Federal; I-Indian; S-State; P-Fee. If Federal or Indian, add Lease Number.

#59 30-039 - 07537

# 128 30-039 - 23777

# 528 30-039 - 24818

## DATA SHEET FOR DEEP GROUND BED CATHODIC PROTECTION WELLS NORTHWESTERN NEW MEXICO

(Submit 3 copies to OCD Aztec Office)

Operator MERIDIAN OIL	Location: Unit_SW_Sec 27 Twp_29 Rng_7
Name of Well/Wells or Pipeline Service	ed <u>SAN JUAN 29-7 UNIT #59, #128, #528</u>
	cps 103w
Elevation 6855' Completion Date 12/15/62	Total Depth 125' Land Type* N/A
Casing, Sizes, Types & Depths	N/A
If Casing is cemented, show amounts &	types used N/A
If Cement or Bentonite Plugs have bee	n placed, show depths & amounts used
	th description of water when possible:
Fresh, Clear, Salty, Sulphur, Etc.	
Depths gas encountered: N/A	DECEIVE
Type & amount of coke breeze used:	850 lbs.
Depths anodes placed: 105', 99', 93', 87	MAY 3 1 1991
Depths vent pipes placed: N/A	OIL CON. DIV.
Vent pipe perforations: N/A	9131. 3
Remarks: gb #1	

If any of the above data is unavailable, please indicate so. Copies of all logs, including Drillers Log, Water Analyses & Well Bore Schematics should be submitted when available. Unplugged abandoned wells are to be included.

<sup>\*</sup>Land Type may be shown: F-Federal; I-Indian; S-State; P-Fee. If Federal or Indian, add Lease Number.