



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office State of
Lease No. 0711
Unit Storey

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
DEC 18 1956
U. S. GEOLOGICAL SURVEY
WASHINGTON, D. C.
December 11, 1956

Well No. 2-2 is located 233 ft. from N line and 234 ft. from E line of sec. 27
SS Section 27 231 21 234
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Antes P.C. Est. San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6052 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12-9-56, Total Depth 2335'.
Run 73 joints 5 1/2", 15.50#, J-59 casing (2335') set at 2335' with 50
cords regular cement, 50 cords Portland, 1/2 gal, followed by 50 cords reg.
cement, 1/4 gal. Wicoma per sack.
Hold 1000# for 30 minutes.
Top of cement by temperature survey at 1320'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 977
Demington, New Mexico

By ORIGINAL SIGNED F.W. BOYD
Title Petroleum Engineer