



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4-23-08 Operator Burlington Res. API # 30-0 39-25709

Property Name San Juan 297 UH Well # 157 Location: Unit 0 Sec 4 Twn 29 Rge 7

Land Type:

State _____
Federal ☒
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒
Pressure observation _____

Temporarily Abandoned Well (Y/N): 6-13-03 TA Expires: 4-23-2013

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 620 psi. for 30 mins. Test passed/failed

REMARKS:

Cased iron bridge plug set at 2990' DIST. 3


OIL CONS. DIV.

By JACK D. DICKHEAD Witness Monica Luchling
(Operator Representative) (NMOCD)

RCVD APR 24 '08

(Position)

Revised 02-11-02



Bullington
GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

5522 ut #157

30 049.25/69

4123-7
BIRCHFIELD
BR 2221

APR 24 05