



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-23-08 Operator Burlington Res API #30-0 39-25709
Property Name San Juan 29764 Well No. 157 Location: Unit 0 Section 4 Township 29 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing ✓/A Intermediate ✓/A Casing 3 1/2 Bradenhead 3 1/2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME					
5 min					3 1/2
10 min					3 1/2
15 min					3 1/2
20 min					3 1/2
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD APR 24 '08

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1/2

INTERMEDIATE ✓/A

REMARKS:

Nothing when opened.

DIST. 3

By Jack P. Blackwell
(Position)

Witness Monica Kuchling

E-mail address _____