

(Position)

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District lil/3distric.htm

## BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 4-9-08	Operator_	Manana API#	API #30-0 <u>45 - /3089</u>	
Property Name Cook	Cook Well No. 2 Location: Unit // Section 22 Township 29 Range //			
Well Status(Shut-In or Producing) Tubing 10 Intermediate 14 Casing 0 Brandenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: TIME INTERMEDIATE	CASING	BRADE FLOW	NHEAD VED	INTERMEDIATE FLOWED
5 minutes /	0	Steady Flow		
10 minutes	0	Surges_		
15 minutes	0	Down to Nothing		
20 minutes	6	Nothing		ys/A
25 minutes	0	Gas		
30 minutes	O	Gas & Water		
)		Water		
It bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN BRADENHEAD 6 INTERMEDIATE 14  REMARKS:  REMARKS:				
			/ig oil	CONS. DIA. DIG.
20, 511101 68 1 32				
By Figs F. Witness				