



OIL & NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1900 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enrwd.state.nm.us/ocd/District/EU3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 19-08 Operator Chevron MidCont API #30-0 39-07068

Property Name Pencon Unit Well No. 54 Location: Unit 3 Section 14 Township 22N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 37.3 Intermediate - Casing 38.0 Bradenhead 0.0 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
5 min	0.0		38.0			
10 min	0.0		38.0			
15 min	0.0		38.0			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psi INTERMEDIATE _____

REMARKS: Found 0.0 Psi g To Flow.

by William Hattell Witness _____

(Position) _____

mail address _____

