& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 17-08 Operator Chevron MidCont API #30-039-25179

Property Name Remson Unit Well No. 159 M Location: Unit F Section 18 Township 27N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 40.0 Intermediate — Casing 71.9 Bradenhead 0.0 Psig

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
5 min	0.0		71.9		
10 min	0.0		71.9		
15 min	0.0		71.9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

RECEIVED
MAY 2008
OIL CONS. DIV DIST 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.0 Psig INTERMEDIATE____

REMARKS: Found 0.0 Psig on Bradenhead.

By J. Willard Hottell Witness____

(Position)

Email address____