



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emvrd.state.nm.us/ocd/District%20District.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13-08 Operator Chevron Midcon API #30-0 39-25187

Property Name Rincon Unit Well No. 133E Location: Unit D Section 14 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 325 Intermediate — Casing 05 Bradenhead 0.1 Psi

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				FLOW CHARACTERISTICS	
	Bradenhead		INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0.0</u>		<u>0.5</u>			Steady Flow
10 min	<u>0.0</u>		<u>0.5</u>			Surges
15 min	<u>0.0</u>		<u>0.5</u>			Down to Nothing ☒
20 min						Nothing
25 min						Gas
30 min						Gas & Water
						Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.1 Psi INTERMEDIATE —

REMARKS:

Found just a whisper No Flow.
New Braden Head Valve.

W. Pelland Hottel

Witness —

(Position)

Oil address —

