



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emurrd.state.nm.us/ocd/District 3/district.htm](http://emurrd.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test March 13, 2008 Operator Chesson Mid Cont API #30-0 39-25187

Property Name Quinon Unit Well No. 133E Location: Unit D Section 14 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 159.6 Intermediate 144.9 Casing 159.9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Drill Completion

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>159.6</u>		
			<u>144.9</u>		
10 min	<u>0</u>		<u>159.6</u>		
			<u>144.9</u>		
15 min	<u>0</u>		<u>159.6</u>		
			<u>144.9</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges


Down to Nothing

Nothing ☒

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

By William Hattell

Witness

Sherry B. Sanudo

(Position)

E-mail address