In Lieu of

## **UNITED STATES**

MAY 2 2 2008

Form 316 (June 199		ENT OF INTERIOR AND MANAGEMENT	Bureau of Land Mai		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
Do not u	SUNDRY NOTICE AND se this form for proposals to drill or to deepen o		3	5.	Lease Designation and Serial No. SF-078764
	TO DRILL" for perm	t for such proposals		6.	If Indian, Allottee or Tribe Name
	SUBMIT IN T	RIPLICATE		7.	If Unit or CA, Agreement Designation ROSA UNIT
1.	Type of Well Oil Well X Gas Well Other			8.	Well Name and No. ROSA UNIT #17A
2.	Name of Operator WILLIAMS PRODUCTION COMPANY			9.	API Well No. 30-039-26272
3.	Address and Telephone No. PO BOX 3102 MS 25-4, TULSA, OK 74101 (918) 573-3046			10.	Field and Pool, or Exploratory Area BLANCO MV
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 790' FSL & 1450' FEL, SW/4 SE/4, SEC 20-31N-05W				11.	County or Parish, State RIO ARRIBA, NEW MEXICO
	CHECK APPROPRIA	TE BOX(s) TO INDICATE NA	TURE OF NOTICE, REP	ORT, OR O	THER DATA
	TYPE OF SUBMISSION TYPE				
	Notice of Intent	Abandonment			Change of Plans

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertunent dates, including estimated date of starting any proposed work. If well is 13. directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Recompletion

Plugging Back

Casing Repair

Altering Casing

RCVD MAY 28 '08 OIL CONS. DIV. DIST. 3

(Note: Report results of multiple completion on Well Completion or Recompletion Report

**New Construction** Non-Routine Fracturing

Water Shut-Off

Dispose Water

and Log form.)

Conversion to Injection

Completed remedial work for non-producing well evaluation.

X Subsequent Report

Final Abandonment

- 1. 4/1/2008; Slickline tag for fill or scale across perforations. RIH with 1.906 guage ring to seat nipple at ~5880 ft. RIH with 1.25 drive down bailer to 6009 ft., no sample. Tag @ 6009' SLD, approximately 26 ft. below bottom producing perf.
- 3/7/2008-3/22/2008; Swabbing unit swabbed on well for 11 days. No progress, recovered 200+ bbls of fluid and fluid level remained at ~3100 ft.

Williams will evaluate this information and make a decision to install a beam pumping unit system, plug back and re-complete up hole, or plug and abandon well.

14.	I hereby certify that the foregoing is true and correct  Signed Achil Lipperd	Title Engineering Technician	Date	May 20, 2008
	(This space for Federal or State office use)			
	Approved by	Title		Date
	Conditions of approval, if any:			ACCEPTED FOR THE COLD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fict thiose confirmated any false. statements or representations as to any matter within its jurisdiction.



## ROSA UNIT #17A BLANCO MESAVERDE

Spud date: 5/26/00 Location: Completed: 7/10/00 790' FSL and 1450' FEL First Delivery: 9/14/00 SW/4 SE/4 Sec 20(O), T31N R05W Rio Arriba, New Mexico Elevation: 6412' GR 6 jts 9-5/8", 36#, K-55, ST&C csg. Landed @ 295' Cemented with 150 sx cmt Top \_\_\_\_ Depth Pictured Cliffs 3310' TIW liner hanger. TOL @ 3639' Lewis 3736' CliffHouse 5504' Menefee 5534' 82 jts 7", 20#, K-55, ST&C csg. Landed @ 3751'. Point Lookout 5761' 4700' Float @ 3703'. Cemented with 600 sx cmt. 5746' 190 jts 2-3/8", 4.7#, J-55, EUE, 8rd tbg w/ 1/2" mule shoe on bottom and SN 1 jt up. Landed @ 5919' **STIMULATION** CliffHouse/Menefee: 4700' - 5746' (32, 0.38" holes) Frac with 80,000# 5760' 20/40 sand in 1895 bbls slick water. 5981' Point Lookout: 5760' - 5981' (30, 57 jts 4-1/2", 10.5#, K-55 ST&C csg. Landed @ 0.38" holes) Frac with 79,840# 20/40 3639' - 6199'. Latch collar @ 6178' & marker jt @ sand in 2099 bbls slick water. 5516'. Cemented with 270 sx cmt TD @ 6199'

Hole Size	Casing	Cement	Volume	Top Of CMT
12-1/4"	9-5/8",36#	150 sx	209 cu. Ft.	surface
8-3/4"	7", 20#	600 sx	1137 cu ft.	surface
6-1/4"	4-1/2",10.5#	270 sx	395 cu. Ft.	3639'

PBTD @ 6050'