



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-17-08 Operator Susan Sullivan/Lizard API #30-0 45 09055
Property Name Sangre De Cristo Well No. #1 Location: Unit D Section 34 Township 30N Range 11W
Well Status (Shut-In or Producing) Tubing 20 Intermediate N/A Casing 45 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>5</u>		<u>45</u>	Steady Flow	<u>N/A</u>
10 minutes	<u>1</u>		<u>46</u>	Surges	<u>N/A</u>
15 minutes	<u>0</u>		<u>45</u>	Down to Nothing <u>X</u>	<u>N/A</u>
20 minutes	<u>0</u>		<u>45</u>	Nothing	<u>N/A</u>
25 minutes	<u>0</u>		<u>45</u>	Gas	<u>N/A</u>
30 minutes	<u>0</u>		<u>45</u>	Gas & Water	<u>N/A</u>
				Water	<u>N/A</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD JUN 9 '08
OIL CONS. DIV.

5 MINUTE SHUT-IN BRADENHEAD 1 INTERMEDIATE N/A

DIST. 3

REMARKS:

By Art Sullivan Witness _____
operator
(Position)

E-mail address lizard35@wildblue.net