submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED
MAY 27 2008

Bureau of Land Management Farmington Field Office

	Sundry Notices and Reports on Wells		-4406
		5.	Lease Number
1.	Type of Well GAS	6.	SF - 078998 If Indian, All. or Tribe Name
2.	Name of Operator	7.	Unit Agreement Name San Juan 32-7 Unit
	CONOCOPHILLIPS Company	<del></del> 8.	Well Name & Number
3.	Address & Phone No. of Operator		San Juan 32-7 Unit 20
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4	Landing of Well Feetogs See T D M	<del></del>	30-045-33698
4.	Location of Well, Footage, Sec., T, R, M  Unit K (NWSW), 1340' FSL & 665' FWL, Section 18, T31N, R7W, NMPM	10.	Field and Pool Blanco MV/Basin DK
		11.	County and State San Juan Co., NM
12	. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	OTHER	DATA
	Type of Submission Type of Action  Notice of Intent Abandonment Change of Plans X C	Other – Casii	
	Recompletion New Construction  X Subsequent Report Plugging Non-Routine Fracturing		RCVD MAY 30 '08
	Casing Repair Water Shut off Altering Casing Conversion to Injection		OIL CONS. DIV.
Dr 10 Le Ta H2 Sta w/:	/25/08 MIRU AWS 301. NU BOP test — Good. PT csg to 600# 30 min. RIH w/8 3/4" bit. illed ahead to 3850'. RIH w/93 jts, 7", 20#, J-55, ST&C csg & set @ 3840'. RU cmt. 5/3/08 bbl Mud Clean, 10bbl FW. Scavenger — 19sx (57cf-10bbl) Premium Lite w/CaCl2, Cellop ad 483sx (1029cf-183bbl) Premium Lite Cement w/3% CaCl, .25 #/sx CelloFlake, 5 #/sx Lil 90 sx(124cf-22bbls) Type 3 Cement w/1% CaCl, .25 #/sx CelloFlake, & .2% FL52. Dro CO. Bumped plug to 1050#. Plug down @ 11:13 5/3/08. Open Stage Collar w/2006#. Circ 1 age 2 Pumped pre-flush of 10 bbls FW/10 bbls MC/10 bbls FW. Pumped Scavenger 19 sx(33% CaCl, .25 #/sx CelloFlake, 5 #/sx LCM-1, .4% FL52, & .4% SMS. Dropped plug @ 16 mped plug. Closed stage collar, circ 30 bbls cement to surface. RD cementers.	8 Stage 1 bhane Flak CM -1, .4 pped plug 5 <u>bbls</u> cer 57cf-10bb	- Preflush w/10bbl FW, ses, FL-52, LCM-1, SMS. 4% FL52, & .4% SMS. g & displaced w/50 bbls ment to surface. Circ hole. ols) Premium Lite Cement
ahe Pu Ce #/s	1/08 PT 7" csg 1500#/30 min – good test. RIH w/6 ¼" bit. Tag cement @ 2818'. D/O cemercad to 8138'(TD). TD reached on 5/6/08. circ hole. RIH w/197 jts 4 ½" 11.6# L-80 casing symped pre-flush of 10 bbls Chem wash/2 bbls FW. Pumped Scavenger 9 sx(27cf-5bbls) Prello-Flake, .3% CD-32, 6.25 #/sx LCM-1 & 1% FL-52. Tail- Pumped 306 sx(606cf-108 bbl x Cello-Flake, .3% CD-32, 6.25 #/sx LCM-1, & 1% FL-52. Dropped plug @ 16:22 5/7/08. rg held @ 1330#. RD cement.	set @ 81 <u>4'</u> mium Lite s) premiu Displaced	7'. RU to cement. 5/6/08 HS FM Cement w/.25 #/sx m Lite HS FM Cement w/.25 d w/127 bbls H2O. Bumped
PT 14.	will be conducted by completion rig & recorded on next report, Report TOC.  I hereby certify that the foregoing is true and correct.	138, <	8147, blease Lenge
Sig	ned Micey Willowar Tracey N. Monroe Title Regulatory Technic	ian l	Date <u>05/27/08</u>
AP	nis space for Federal or State Office use) PROVED BYTitle	,	Date ACCEPTED FOR RECORD
Title	NDITION OF APPROVAL, if any:  18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to mike any department or agency of inted States any talse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	n	MAY 2 9 2008