



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-26-08 Operator Burlington Res API #30-0 39-25331

Property Name SS306 Unit Down Well No. 2 Location: Unit C Section 33 Township 30 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 80 Intermediate N/A Casing 180 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>RCUD JUN 26 '08</u>
Nothing	<u>OIL CONS. DIV.</u>
Gas	<u>DIST. 3</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

blew down in 9 seconds

By R.G. [Signature]
Co. Rep.
(Position)

Witness

Monica Kuchling

E-mail address _____