



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

RCVD JUL 8 '08
OIL CONS. DIV.
DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 7-8-08 Operator Burlington Res API # 30-0 39-24530

Property Name San Juan 30-6 L.H. Res Well # 1 Location: Unit Sec 24 Twn 30 Rge 7

Land Type:

State
Federal /
Private
Indian

Well Type:

Water Injection
Salt Water Disposal
Gas Injection
Producing Oil/Gas
Pressure observation /

Temporarily Abandoned Well (Y/N): / TA Expires: 7-8-2013

Casing Pres. 0
Bradenhead Pres. Open
Tubing Pres. 0
Int. Casing Pres. N/A

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres.

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

Pressure test results at 2975
top of plug at 2848
Bot plug at 3024
Test retrievable bridgplug set at 2940

Threads on Btl valve had unable to put gasket and had to
test later.
By R. E. [Signature] (Operator Representative) Witness Monica [Signature] (NMOCD)

Co Rep C/P
(Position)

Revised 02-11-02

