RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL 08 2008

			Bureau of Land Management
	Sundry Notices and Reports on Wells		Farmington Field Office
		5.	Lease Number
			NM-012710
1.	Type of Well	6.	If Indian, All. or
	GAS		Tribe Name
		7.	Unit Agreement Name
2.	Name of Operator		San Juan 30-6 Unit
	BURLINGTON RESCURCES OIL & GAS COMPANY LP		
	HESOURCES OIL & GAS COMPANY LP	8.	Well Name & Number
3.	Address & Phone No. of Operator		San Juan 30-6 Unit 402 PO
	P.O. Box 4289, Farmington, NM 87499	9.	API Well No.
-			30-039-24015
4.	Location of Well, Footage, Sec., T, R, M	10	
	Unit K (NESW), 1455' FSL & 1455' FWL, Section 15, T30N, R07W, NMPM	10.	Field and Pool Basin Fruitland Coal
R		11.	County and State
•			San Juan Co., NM
6/20 w/tl pac was retr 300	X Subsequent Report Plugging Water Shut off Final Abandonment Altering Casing Repair Conversion to Injection Describe Proposed or Completed Operations 6/08 MIRU AWS 473. ND WH, NU BOP. PT - OK. Pull tbg hanger & LD 3 jts tbg. TI bg. PU & RIH w/RBP & retrievable packer & set @ 3006' (RBP) & 2990' (pkr). Pt RBI ker & roll hole w/120 bbls produced water. 6/30/08 PT casing from 3006' to surface to 5 witnessed by Monica Kueling w/NMOCD. OCD kept chart and it will be posted on OCT ieved RPB. POOH w/tools. 7/1/08. RIH w/new tbg — 96 jts 2-3/8", 4.7# J-55 tbg & tens 107'. ND BOP, set & land packer w/10000#. NU WH. Load casing w/97 bbls packer fluid eased rig 7/1/08.	odown tbg 00#/30 min Donline. ion packer	to 500#- good. Released n. Good charted test. Test Unload casing w/air & t. EOT @ 3040' w/packer @
Sig (Th	I hereby certify that the foregoing is true and correct. ned	pecialist	Date <u>7/7/08</u>

ACCEPTED FOR HEIGHD

JUL 14 2008

