

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX: (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6-10-08 Operator Dugan Production Corp. API # 30-045-20272  
Property Name Moore Well No 1 Location Unit A Section 7 Township 30N Range 8W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 85 Intermediate 0 Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		85	0	85	
10 minutes	0		85	0	85	
15 minutes	0		85	0	85	
20 minutes	0		85	0	85	
25 minutes	0		85	0	85	
30 minutes	0		85	0	85	

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
X	X


**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



By Ashley Perkins  
Switcher  
(Position)

Witness \_\_\_\_\_