

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emrnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-08 Operator Dugan Production Corp. API # 30-045-32630
Property Name State Com Well No 1C Location: Unit J Section 16 Township 32N Range 12W
Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		75			
10 minutes	0		75			
15 minutes	0		75			
20 minutes	0		75			
25 minutes	0		75			
30 minutes	0		75			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Down to Nothing	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Nothing



By

Archie Luevano

Witness

Switcher

(Position)