UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL 3 1 2008

DUREAU OF LAND MANAGEMENT	Burger	a territoria de se de
Sundry Notices and Reports on Wells		التحقيق والمواجع المياس والمراجع المراجع
	5.	Lease Number USA SF-079391
I. Type of Well GAS		If Indian, All. or Tribe Name
2. Name of Operator	7.	Unit Agreement Name
BURLINGTON		
RESCURCES OIL & GAS COMPANY LP	 8.	San Juan 27-5 Unit Well Name & Number
3. Address & Phone No. of Operator		
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 27-5 Unit 120 API Well No.
		30-039-30518
4. Location of Well, Footage, Sec., T, R, M 2626' Surf: Unit L (NWSW), 2656' FSL & 185' FWL, Section 7, T27N, R5W, NMPM		Field and Pool Basin Dakota
BH: Unit H (SENE), 2586' FNL & 20' FEL, Section 7, T27N, R5W, NMPM		
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT Type of Submission Type of Action		County and State Rio Arriba Co., NM ATA
Type of Submission Type of Action		Rio Arriba Co., NM ATA
Type of Submission Notice of Intent Abandonment Change of Plans X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off	Other – Spud R 7 ½" bit to 24 Pump 380 s	Rio Arriba Co., NM ATA Report 40'. Spud TD reached 7/2 sx (297 cf – 86 bbl slurry
Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 7/27/08 MIRU Aztec 730. 7/28/08 spud w/12 ½¹¹bit pilot hole & drilled to 240'. Ream w/1' Circ hole. RIH w/5 jts, 13 3/8'', 48#, H-40 ST&C csg & set @ 233'. Pre-flush 20 bbls FW. III, w/2% CACL2, .25# Cellophane flake. Dropped plug and displaced w/40 bbls FW. Circ PT will be conducted by drilling rig & reported on next report.	Other – Spud R 7 ½" bit to 24 Pump 380 s	Rio Arriba Co., NM ATA Report 40'. Spud TD reached 7/2 sx (297 cf – 86 bbl slurry to surface. WOC RCUD AUG 4'OB
Type of Submission Notice of Intent Abandonment Recompletion New Construction New Construction Non-Routine Fracturing Casing Repair Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 7/27/08 MIRU Aztec 730. 7/28/08 spud w/12 ½'bit pilot hole & drilled to 240'. Ream w/1' Circ hole. RIH w/5 jts, 13 3/8", 48#, H-40 ST&C csg & set @ 233'. Pre-flush 20 bbls FW. III, w/2% CACL2, .25# Cellophane flake. Dropped plug and displaced w/40 bbls FW. Circ	Other – Spud R 7 ½" bit to 24 Pump 380 s	Rio Arriba Co., NM ATA Report 40'. Spud TD reached 7/2 sx (297 cf – 86 bbl slurry to surface. WOC RCVD AUG 4'OP OIL CONS. DIV.
Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 7/27/08 MIRU Aztec 730. 7/28/08 spud w/12 ¼'bit pilot hole & drilled to 240'. Ream w/1' Circ hole. RIH w/5 jts, 13 3/8", 48#, H-40 ST&C csg & set @ 233'. Pre-flush 20 bbls FW. III, w/2% CACL2, .25# Cellophane flake. Dropped plug and displaced w/40 bbls FW. Circ PT will be conducted by drilling rig & reported on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct.	Other – Spud R 7 ½" bit to 2- Pump 380 s 38 bbls cmt	Rio Arriba Co., NM ATA Report 40'. Spud TD reached 7/2 sx (297 cf - 86 bbl slurry to surface. WOC RCUD AUG 4'08 OIL CONS. DIV. DIST. 3
Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 7/27/08 MIRU Aztec 730. 7/28/08 spud w/12 ½¹¹bit pilot hole & drilled to 240'. Ream w/1' Circ hole. RIH w/5 jts, 13 3/8'', 48#, H-40 ST&C csg & set @ 233'. Pre-flush 20 bbls FW. III, w/2% CACL2, .25# Cellophane flake. Dropped plug and displaced w/40 bbls FW. Circ PT will be conducted by drilling rig & reported on next report. APD/ROW	Other – Spud R 7 ½" bit to 2- Pump 380 s 38 bbls cmt	Rio Arriba Co., NM ATA Report 40'. Spud TD reached 7/2 sx (297 cf - 86 bbl slurry to surface. WOC RCUD AUG 4'08 OIL CONS. DIV. DIST. 3
Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 7/27/08 MIRU Aztec 730. 7/28/08 spud w/12 ¼'bit pilot hole & drilled to 240'. Ream w/1' Circ hole. RIH w/5 jts, 13 3/8", 48#, H-40 ST&C csg & set @ 233'. Pre-flush 20 bbls FW. III, w/2% CACL2, .25# Cellophane flake. Dropped plug and displaced w/40 bbls FW. Circ PT will be conducted by drilling rig & reported on next report. APD/ROW 14. I hereby certify that the foregoing is true and correct.	Other – Spud R 7 ½" bit to 24 Pump 380 s 38 bbls cmt	Rio Arriba Co., NM ATA Report 40'. Spud TD reached 7/2 sx (297 cf - 86 bbl slurry to surface. WOC RCUD AUG 4'08 OIL CONS. DIV. DIST. 3

ACCEPTED FOR RECORD

AUG 0 1 2008

FARRAMENTON FIELD OFFICE
BY IL Salvess

