UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL 3 1 2008

DUREAU OF LAND MANAGEM	.1514 1	Pr		· mani
Sundry Notices and Reports on Wells				3017 11.02
			5.	Lease Number
. Type of Well			6.	USA SF - 079391 If Indian, All. or
GAS			0.	Tribe Name
. Name of Operator			7.	Unit Agreement Name
BURLINGTON				
RESOURCES OIL & GAS COM	PANY LP			San Juan 27-5 Unit
Address & Phone No. of Operator			- 8.	Well Name & Number
-				San Juan 27-5 Unit 906
PO Box 4289, Farmington, NM 87499 (505)	326-9700		9.	API Well No.
			_	30-039-30305
Location of Well, Footage, Sec., T, R, M			10.	Field and Pool
Surf: Unit G (SWNE), 1699' FNL & 1865' F			Blanco MV/Basin DK	
BH: Unit G (SWNE), 2280' FNL & 1705' FF	L., Section 8, T27	N, R5W, NMPM	11.	County and State
				Rio Arriba Co., NM
X Subsequent Report Plugging Casing Repa	nir Water Shu	ne Fracturing it off		RCVD AUG 5'08 OIL CONS. DIV.
Final Abandonment Altering Ca	sing Conversion	n to Injection		DIST. 3
13. Describe Proposed or Completed Opera	tions			
7/17/08 MIRU AWS 711. NU BOP. PT csg to 600# 30/head to 3765'intermediate. Circ hole. RIH w/87 jts 7" 2.5 W, 10bbls Mud Clean, 10bbls FW. Pumped Scavenger 2.5 Elake, .4% FL-52, 5 #/sx LCM-1, .4% Sodium Metasilica 2.5 ** #/sx Cello-flakes, .4% FL-52, 5 #/sx LCM-1, & .4% 2.25 ** ** Cello-flakes, .2% FL-52. Dropped plug and displa 2.7/22/08 PT csg to 1500# 30/min -good test. RIH w/ 6 ** ** RIH w/188 jts 4 **/2" 11.6# L-80 LT & C casing set @ 789 ** ** Cavenger -10 sx(30cf-5 bbls) Premium Lite HS FM cer 594cf-106bbls) Premium Lite HS FM Cement w/.25 **/sbls FW & first 25bbls sugar water. Bumped plug. RD, I	3# L-80 csg set @ 3°. 20 sx(60cf-11bbls) Cate. Lead- pumped 4 Sodium Metasilicate aced w/146bbl water 4" bit. D/O cement. 1 00'. RU to cement. 0 ment w/.3% CD-32, ax Cello-Flake, 6.25 # RR @ 06:00 07/27/0	757'. RU to cement. 07/22/08 Class G Cement w/8% Benton 90 sx(1044cf-186bbls) Class c. Tail- pumped 90 sx(124cf-2), circulated 66 bbls cement to Drill ahead to 7895' TD. TD 7/26/08 Pumped pre-flush of 1% Fl-52, .25#/sx Cello-flake/sx LCM-1, .3% CD-32, 1%	. Pumped ite, 3% C G Cemer 22bbls) C surface. reached o 10 bbls c e, 6.25 #/s	pre-flush of 10 bbls CaCl2, .25 #/sx Cello- at w/8% Bentonite, 3% CaCl2 Class G Cement w/1% CaCl2, con 07/25/08. Circ hole. 07/26/ hem. Wash & 2bbl FW. Pun fix LCM-1. Tail- 300 sx
T will be conducted by completion rig. PT & TOC will	be recorded on next	report.		
4. I hereby certify that the foregoing is true and cor	rect.	•		
	Sasha Spangler	Title Regulatory Tech	nician	Date <u>07/30/08</u> .
This space for Federal or State Office use) PPROVED BY	Title		ICCE P	Pate por research
CONDITION OF APPROVAL, if any: ttle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully a lighted Stream fields textition in the analysis of the property of the p			-, A	11001
United States any false, fictitious or fraudulent statements or representations as to		ยเ	A	UG 0 4 2008
	NMOCD	F	ARMIN	STON FIEDD OFFICE

P.