



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-8-08 Operator Burlington Resources API #30-0 45-10044

Property Name EPNG CORP Well No. 2 Location: Unit M Section 32 Township 31 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 15 Intermediate 18 Casing 17 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			<u>17</u>		<u>17</u>
10 min					<u>17</u>
15 min					<u>17</u>
20 min					<u>16.9</u>
25 min					<u>16.9</u>
30 min					<u>16.9</u>

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>yes</u>	
Surges		
Down to Nothing	<u>no</u>	
Nothing		
Gas		RCVD AUG 8 '08 OIL CONS. DIV.
Gas & Water		DIST. 3
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 18

REMARKS:

Puff on bradenhead when opened
intermediate blew crown in 3 seconds
blew head 3 seconds then med. blow tested
time.

By James Simpson

Witness Maria Cukling

(Position)

E-mail address _____