District J
1625 N French Dr , Hobbs, NM 88240
District JI
1301 W Grand Avenue, Artesia, NM 88210
District JII
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Proposed Alternative Method Permit or Closure Plan Application

Type of action:

| X | Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method
| Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method

Instructions: Please submit one application (Form C-144) per in	ndividual pit, closed-loop system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of lie	ability should operations result in pollution of surface water, ground water or the ply with any other applicable governmental authority's rules, regulations or ordinances
Operator: Dugan Production Corp.	
Address: 709 East Murray Drive, Farmington, New Me	· · · · · · · · · · · · · · · · · · ·
Facility or well name: Mayre #1	DIST, 3
API Number: 30-045-09083	OCD Permit Number:
U/L or Qtr/Qtr P Section 31 Township 30	
	Longitude 108.3431 West NAD: 図1927 🗌 1983
Surface Owner: 🗵 Federal 🗌 State 🔲 Private 🔲 Tribal Trust or Indian A	Allotment
Pit: Subsection F or G of 19.15.17.11 NMAC	Closed-loop System: Subsection H of 19.15.17.11 NMAC
Temporary: Drilling Workover	☐ Drying Pad ☐ Tanks ☐ Haul-off Bins ☐ Other
☐ Permanent ☐ Emergency ☐ Cavitation	☐ Lined ☐ Unlined
Lined Unlined	Liner type: ThicknessmilLLDPE _ HDPE _ PVC
Liner type: Thicknessmıl	Other
Other String-Reinforced	Seams: Welded Factory Other
Seams: Welded Factory Other	Volume:bblyd³
Volume:bbl Dimensions: Lx Wx D	Dimensions: Lengthx Width
X Below-grade tank: Subsection I of 19.15.17.11 NMAC	Fencing: Subsection D of 19.15.17.11 NMAC
Volumebbl	☐ Chain link, six feet in height, two strands of barbed wire at top
Type of fluid: Produced H2O	Four foot height, four strands of barbed wire evenly spaced between one and
Tank Construction material. Steel	four feet Other Fencing $\frac{4'=3'}{1}$ Hog wire + 1 Strand barbed wire
☐ Secondary containment with leak detection	Netting: Subsection E of 19.15.17.11 NMAC
☐ Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off	☐ Screen ☐ Netting ☒ Other Expanded Metal
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Visible sidewalls only ☐ Visible sidewalls only	☑ Monthly inspections
Visione side wans only	Signs: Subsection C of 19.15.17.11 NMAC
X Other No visible sidewalls, Leak detection	☑ 12'x24', 2' lettering, providing Operator's name, site location, and
Liner type: Thicknessmil HDPE PVC	emergency telephone numbers
Other	Signed in compliance with 19.15.3.103 NMAC
Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration	Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required Please refer to 19 15.17 NMAC for guidance
of approval.	Please check a box if one or more of the following is requested, if not leave
•	blank: X Administrative approval(s): Requests must be submitted to the
	appropriate division district or the Santa Fe Environmental Bureau office for consideration of approval.
	Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above-grade tanks associated with a closed-loop system.	-
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search, USGS: Data obtained from nearby wells	☐ Yes 🗵 No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☒ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☒ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No 図 NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes 🗵 No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☒ No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☒ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☒ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ☒ No
Within a 100-year floodplain FEMA map	☐ Yes 🏻 No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the dattached. □ Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.15 NMAC □ Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.12 □ Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC □ Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC □ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC □ Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC □ Previously Approved Design (attach copy of design) API Number: □ Or Permit Number: □ Or P	ocuments are
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC	
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the dot attached. Geologic and Hydrogeologic Data (required for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of Siting Criteria Compliance Demonstrations (required for on-site closure) - based upon the appropriate requirements of 19.15.17.10 Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	° 19.15.17.15
Previously Approved Design (attach copy of design) API Number:	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC	
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the do	ocuments are
attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.15 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17 10 NMAC	
 ☐ Climatological Factors Assessment ☐ Certified Engineering Design Plans - based upon the appropriate requirements of 19.15 17.11 NMAC ☐ Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC ☐ Quality Control/Quality Assurance Construction and Installation Plan 	-
 □ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC □ Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC □ Nuisance or Hazardous Odors, including H₂S, Prevention Plan □ Emergency Response Plan □ Oil Field Waste Stream Characterization 	
 ☐ Monitoring and Inspection Plan ☐ Erosion Control Plan ☐ Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC 	
Proposed Closure: 19.15.17.13 NMAC Type: Drilling Workover Emergency Cavitation Permanent Pit Below-grade Tank Closed-loop System Closed-loop System Drilling Closed-loop System Drilling System Closed-loop System Drilling System Drilling System Drilling Closed-loop System Drilling System Drillin	Alternative
Proposed Closure Method: Waste Excavation and Removal On-site Closure Method (only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial	
Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for cor	nsideration)
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application - Visual inspection (certification) of the proposed site, Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society, Topographic map 	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No

Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Edicorure plan. Please indicate, by a check mark in the box, that the documents are attached. ☐ Protocols and Procedures - based upon the appropriate requirements of 19.15 17.13 NMAC ☐ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection I Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection I of 19.15.17.13 ☐ Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17	section F of 19.15.17.13 NMAC ubsection H of 19.15.17.13 NMAC NMAC .13 NMAC
Waste Removal Closure For Closed-loop Systems That Utilize Haul-off Bins Only: (19.15.17.1 or facilities for the disposal of liquids, drilling fluids and drill cuttings.	3.D NMAC) Instructions: Please indentify the facility
	Permit Number:
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items	
by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.1 Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of Construction and Design of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.13 NMAC Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15.17.13 Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17	19.15.17.13 NMAC nents of 19.15.17.11 NMAC section F of 19.15.17.13 NMAC 9.15.17.13 NMAC case on-site closure standards cannot be achieved) NMAC NMAC
Operator Application Certification:	
I hereby certify that the information submitted with this application is true, accurate and complete to	the best of my knowledge and belief.
Name (Print): Kurt Fagrelius Title: Vic	e President, Exploration
Signature Kurt Fagrelin Date.	8-5-2008
	505-325-1821 (O), 505-320-8248 (C)
	Approval Date: 8-19-08
OCD Representative Signature: Title: Eau. 10 Spec OCD Permit Nu	mber:
OCD Representative Signature: Title: Eurico Spec OCD Permit Nu Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 N	mber:
OCD Representative Signature: See OCD Permit Nu Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 N Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain	mber: IMAC mpletion Date:
OCD Representative Signature: Title:	mber: MMAC mpletion Date: od ned to the closure report. Please indicate, by a check
OCD Representative Signature: Title:	mber: MMAC mpletion Date: od ned to the closure report. Please indicate, by a check
Closure Report (required within 60 days of closure completion): Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method If different from approved plan, please explain Closure Report Attachment Checklist: Instructions: Each of the following items must be attach mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Certification: I hereby certify that the information and attachments submitted with this closure report is true, accurbelief. I also certify that the closure complies with all applicable closure requirements and condition	MMAC mpletion Date: od ned to the closure report. Please indicate, by a check NAD: 1927 1983 ate and complete to the best of my knowledge and
Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 N Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Methol If different from approved plan, please explain Closure Report Attachment Checklist: Instructions: Each of the following items must be attack mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Longitude Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is true, accurbed belief. I also certify that the closure complies with all applicable closure requirements and condition	MMAC mpletion Date: od ned to the closure report. Please indicate, by a check NAD: 1927 1983 ate and complete to the best of my knowledge and
Title:	MMAC mpletion Date: od ned to the closure report. Please indicate, by a check NAD:1927 1983 ate and complete to the best of my knowledge and s specified in the approved closure plan

Mayre #1 Hydrogeologic Report

The Mayre #1 is located on Federal land on flats below "Pinon Mesa" on the northwest margin of the San Juan Basin, in San Juan County, New Mexico. The area is characterized as a very flat and arid area on the Kirtland Shale with minimal grass and sage that is bordered by "Bad Lands" topography to the north and housing / industry to the south.

A records search of the NM Office of the State Engineer –iWATERS database was conducted on a three square mile area centered on the Mayre #1 location (Exhibit 2). Eight water wells were located south and west of the proposed below grade tank. The wells were drilled to a depth of between 60 and 1005 feet. The depth to ground water was reported from 52 to 131 feet. The closest water well is 1,950 feet to the southeast. This well was drilled to a depth of 150 feet, depth to ground water was reported at 90 feet and the well yield was 1. The productive interval is either thin, laterally discontinuous sand stringers that can not be traced to offset wells, or fractures in the upper Kirtland Shale. The well is 25 feet in elevation lower than the elevation at the proposed below grade tank. The correlative depth to the same zone at the location of the below grade tank would be 115 feet below the surface. The water wells are privately owned and provide very marginal amounts of water for livestock and agricultural use.

The main source of stock water in the region is encountered in valley-fill deposits in existing arroyos at shallow depths of approximately 15-50 feet below the surface. Also, there are stock ponds located along some of the main arroyos. The proposed below grade tank is not located in an arroyo; the closest arroyo is over 600 feet to the north and it breeches the surface down to a depth of 50 feet.

The Kirtland Shale extends from the surface down to a depth of approximately 435 feet. The interval is comprised of an upper shale member, middle sandstone member (Farmington Ss.) and a lower shale member. There are no sands in the upper and lower shale to contain ground water. The middle sandstone member is poorly developed from 260 down to 285 feet, and does not contain a good quantity or quality of groundwater to justify drilling to. There is Fruitland Sand from 435-460 that would contain ground water but the quality is expected to be poor.

Based on electric open hole logs, the iWATERS database and literature reviewed, depth to ground water ranges from 15-20 feet below the surface in major arroyos in the area. Moving away from the washes, depth to ground water drops rapidly to greater than 200 feet below the surface. At the location of the subject below grade tank, lesser amounts of poor quality ground water might be found at a depth of approximately 115 feet from fractures or thin, discontinuous sand stringers in the upper Kirtland Shale member. Larger quantities of poor quality ground water could be expected from Fruitland sand at 435-460 feet and the Fruitland Coal and Pictured Cliffs Sandstone interval at around 750 feet below the surface.

Excessive drilling depth, unpredictable variations in reservoir quality and water quality have discouraged the drilling of water wells in the in the subject area. Those wells that have been drilled produce only very minimal amounts of poor quality water.

- Stone, W.J., Lyford, F.P., Frenzel, P.F., Mizell, N.H., and Padgett, E.T., 1983, Hydrogeology and water resources of San Juan Basin, New Mexico: New Mexico Bureau of Mines and Mineral Resources Hydrologic Report 6, 70 p.
- Brown, D.R., and Stone, W.J., 1979, Hydrogeology of Aztec quadrangle, San Juan County, New Mexico: New Mexico Bureau of Mines and Mineral Resources Hydrogeologic Sheet 1.
- Levings, G.W., Craigg, S.D., Dam, W.L. Kernodle, J.M., and Thorn, C.R., 1990, Hydrogeology of the San Jose, Nacimiento, and Animas Formations in the San Juan Structural Basin, New Mexico, Colorado, Arizona and Utah: U.S. Geological Survey, Atlas HA-720-A, Sheet 1 and 2.
- Thorn, C.R., Levings, G.W., Craigg, S.D., Dam, W.L., and Kernodle, J.M., 1990, Hydrogeology of the Ojo Alamo Sandstone in the San Juan Structural Basin, New Mexico, Colorado, Arizona and Utah: U.S.G.S, Atlas HA-720-B, Sheet 1 and 2.

	Town	ıship: 3	0N Range:	14W	Sections:	29,30,	31,32	!		•	
	NAD27	X:,	Y:		Zone:		M	Search R	adius:	:	
County:		M	Basin:			(I)	Numt	per:	•	Suffix:	
Owner Na	me: (Firs	st)	WALLES COM AND	(Last)	alah garatingan di Olembayaran ang parabilingan	au tanaga ata	01	Non-Dom	estic	ODomestic	All
PC	DD / Surfac	e Data F	Report	Avg	Depth to W	ater Re	port		Water	Column Repor	t
			Clear Fo	orm [iWATERS	S Menu		Help			
		COLUMN TO THE PARTY OF THE PART			er transporter and the second				oranamin'i Irani.		
			WAT	ER COL	UMN REPOI	RT 08/	01/2	8008			

(quarters are 1=NW 2=NE 3=SW 4=SE) (quarters are biggest to smallest)

Depth Depth Water (in feet)

Tws Rng Sec q q q Zone X Y Well Water Column

No Records found, try again

POD Number

	Town	ıship:	30N	Range:	15W	Sections:	25,3	6			
	NAD27	X:		Y:		Zone:			Search Radius	:	
County:		团	Basin	:				Num	ber:	Suffix:	
Owner Na	ame: (Firs	st)			(Last)	and the second seco		0	Non-Domestic	ODomestic	
P	OD / Surfac	e Data	Report		Avg	Depth to W	/ater F	Report) Wate	er Column Repor	t
				Clear F	orm [iWATERS	S Men	ıu	Help		
			The second secon								

WATER COLUMN REPORT 08/01/2008

(quarters are 1=NW 2=NE 3=SW 4=SE)

(qu	arter	s are	e pro	gge	st	to	smal:	lest)		Depth	Depth	Water	(in feet)
POD Number	Tws	Rng	Sec	q	q ·	q	Zone	x	Y	Well	Water	Column	
SJ 00971 EXPLORE-2	30N	15W	36	1	4	3	W	342253	2100399	524	131	393	
SJ 00971 EXPLORE-1	30N	15W	36	1	4	3	W	342253	2100399	532	102	430	

		FU	D Keports and	Downloads					
	Township:	29N Range:	15W Section	ns: 1			-		
	NAD27 X:	Y:	Zone	: [3	Search R	Radius:			
County:		Basin:		Nun	nber:	Su	ffix:		
Owner Na	ame: (First)		(Last)	C	Non-Dom	estic C) Domesti	e All	
Po	DD / Surface Dat	a Report	Avg Depth to	Water Report		Water Co	olumn Rep	ort	
		Clear For	m iWAŢE	RS Menu	Help				

		WATER	COLUMN REPOI	RT 08/01/20	800				
	(quarters a	are 1=NW 2=NE	3=SW 4=SE)						
	(quarters a	are biggest to	smallest)		Depth	Depth	Water	(in feet)
POD Number		ng Secqqq 5W 01 123	Zone X	Y	Well 1005	Water	Column		

	Townshi	p: 29N	Range:	14W	Sections:	5,6			•	
NA	AD27 X		Y:		Zone:		ä	Search Radius	:	
County:	la se	Basi	n:			M	Num	ber:	Suffix:	
Owner Name:	: (First)	ilikki sirilki ili danin ilikan dalah rahma	delikusis kiristikisi meri alaunduksi	(Last)	dente en la companya de la companya		0	Non-Domestic	ODomestic	All
POD/	Surface D	ata Repor		Avg	Depth to W	/ater F	Report	Wate	r Column Repor	
			Clear F	orm [iWATER	S Men	nu	Help		
				-/			******			

WATER COLUMN REPORT 08/01/2008

(quarters are 1=NW 2=NE 3=SW 4=SE)

	(quarter	s are	e pr	gge	est	: to	smallest)			Depth	Depth	Water	(in feet)
POD Number	Tws	Rng	Sec	q	q	q	Zone	Х	Y	Well	Water	Column	
SJ 02055	29N	14W	05	1	1					150	90	60	
SJ 01883	29N	14W	06	2	3					75	30	45	
SJ 02927	29N	14W	06	2	3	2				150			
SJ 03411	29N	14W	06	3	1	4				60			
SJ 01407	29N	14W	06	3	3	3				70	52	18	

New Mexico Office of the State Engineer Point of Diversion Summary

Back

(quarters are 1=NW 2=NE 3=SW 4=SE) (quarters are biggest to smallest)

POD Number Tws Rng Sec q q q Zone X Y

SJ 02055 29N 14W 05 1 1

Driller Licence: 724 HARGIS, JOHN C.

Driller Name: HARGIS, JOHN C. Source: Shallow Drill Start Date: 05/02/1987 Drill Finish Date: 05/12/1987

Log File Date: 05/15/1987 PCW Received Date:
Pump Type: Pipe Discharge Size:
Casing Size: 4.5 Estimated Yield: 1
Depth Well: 150 Depth Water: 90

Water Bearing Stratifications: Top Bottom Description

80 90 Sandstone/Gravel/Con

Casing Perforations: Top Bottom 80 150

Siting Criteria for the Mayre #1

- 1. Ground water is not less than 50-feet below the bottom of the below grade tank. Ground water is greater than 100-feet below the bottom of the below grade tank.
- 2. The below grade tank is not within 300-feet of a continuously flowing water course, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake (measured from ordinary high water mark). See the attached Topographic map (Exhibit 2) and Visual Inspection Certification of the location and area around the subject below grade tank.
- 3. The below grade tank is not within 300-feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. See the attached Satellite Image (Exhibit 3) and Visual Inspection certification of the location and area around the subject below grade tank.
- 4. The below grade tank is not within 500-feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. See the attached NM Office of the State Engineer iWATERS database search (Exhibit 4) and Visual Inspection certification of the location and area around the subject below grade tank.
- 5. The below grade tank is not located within the incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978 Section 3-27-3, as amended. See the attached Topographic map of the location and area around the subject below grade tank.
- 6. The below grade tank is not located within 500-feet of a wetland. See the attached Topographic map and Visual Inspection Certification of the location and area around the subject below grade tank.
- 7. The below grade tank is not located within the area overlying a subsurface mine. See the attached Mine, Mills and Quarry Map of New Mexico (New Mexico, EMND 2008) (Exhibit 5) showing the location and area around the subject pit.
- 8. The below grade tank is not located within an unstable area. See the attached Topographic map of the location and area around the subject below grade tank.
- 9. The below grade tank is not located within a 100-year floodplain area. See the attached FEMA map (Exhibit 6) of the 100 year floodplain showing the location and area around the subject pit.

Mayre #1 Visual Inspection Certification

I, Kurt Fagrelius, Vice President of Exploration for Dugan Production Corp. 709 East Murray Drive, Farmington, New Mexico hereby certify that I or persons under my direct supervision, prepared the attached exhibits and conducted a Visual Inspection of the location and area around the Mayre #1 below grade tank (Week of July 21, 2008). This application is in full compliance with all siting criteria and standards for below grade tanks established by the State of New Mexico, Energy Minerals and Natural Resources Department 19.15.17.10 NMAC.

Kurt Fagrelius

Kurt Fagrelius





EXHIBIT 3.



	Township: 30N	Range: 14W	Sections: 3	1,32	
NA	AD27 X:	Y:	Zone:	Search I	Radius:
County:	Ba	asin:	Ľ	Number:	Suffix:
Owner Name	: (First)	(Last)		○ Non-Don	nestic ODomestic Al
POD /	Surface Data Rep	port Av	g Depth to Wat	er Report	Water Column Report
		Clear Form (iWATERS N	Menu Help	
end hans all his his his his high and the state of the st		a namadon norr 864 manggapa, nagana anggana agado a mangan mpang mangan anggan			
		WATER CO	LUMN REPORT	08/01/2008	
	/	1-177 0 178 3-0	TT 4 0TT\		

(quarters are 1=NW 2=NE 3=SW 4=SE) (quarters are biggest to smallest) Tws Rng Sec q q q Zone

Depth

Depth Water (in feet)

Y Well Water Column

No Records found, try again


POD Number

	Town	ship:	29N J	Range:	14W	Sections:	5,6				
	NAD27	X:		Y:		Zone:		A	Search Radius	:	
County:		到	Basin:				H	Num	ber:	Suffix:	
Owner Na	ame: (Firs	st)	***************************************	rindi.	(Last)		· · · · · · · · · · · · · · · · · · ·	0	Non-Domestic	ODomestic	All
PC	DD / Surfac	e Data	Report		Avg	Depth to W	ater F	Report	Wate	r Column Repor	1
				Clear Fo	orm [iWATERS	3 Men	ıu	Help		

WATER COLUMN REPORT 08/01/2008

(quarters are 1=NW 2=NE 3=SW 4=SE)

	(quarter	s are	e big	gge	st	to	smallest)			Depth	Depth	Water	(in feet)
POD Number	Tws	Rng	Sec	q	q	q	Zone	X	Y	Well	Water	Column	
SJ 02055	29N	14W	05	1	1					150	90	60	
SJ 01883	29N	14W	06	2	3					75	30	45	
SJ 02927	29N	14W	06	2	3	2				150			
SJ 03411	29N	14W	06	3	1	4				60			
SJ 01407	29N	14W	06	3	3	3				70	52	18	



Mine, Mills and Quarry Map of New Mexico

Dugan Production Corp.

Mayre #1

Taken from the New Mexico Energy, Minerals and Natural Resources Department.

Mining and Minerals Division.


EXHIBIT 6.

Mayre #1 Design and Construction Plan

The Mayre #1 below grade tank will be designed and constructed in accordance with the following requirements:

- 1. Below grade tank will be designed and constructed to contain liquids and solids, prevent contamination of fresh water and protect the public health and environment (Exhibit 7).
- 2. Stockpile topsoil prior to digging pit, keep separate from subsoil and use as final cover and fill when closing pit.
- 3. Sign-12" by 24" with operator name, lease name, well #, location (unit letter, qtr/qtr, Sect., Twp., and Rge.) and emergency phone #'s will be posted on location. Sign will be posted in a location where it can be easily read.
- 4. Fencing around the Mayre #1 below grade tank will be constructed and operated in a manner that prevents unauthorized access and shall be maintained in good condition to protect the public and wildlife. Fencing will include a 4-foot hog wire fencing with two strands of barbed wire or top rail of re-bar or pipe on top. See the attached request for Administrative Approval. The Mayre #1 below grade tank is not located within 1000 feet of a house, school, hospital or church.
- 5. The Mayre #1 below grade tank will be covered with expanded metal, chicken-wire or a metal lid on top of the tank.
- 6. Mayre #1 below grade tank will be designed and constructed to ensure the confinement of liquids and prevent unauthorized releases. Pit will be constructed with a firm foundation and interior slopes, smooth and free of rocks or sharp edges to prevent punctures, cracks or indentations of the liner or tank bottom.
- 7. Mayre #1 below grade tank will be constructed of materials resistant to the tank's particular contents and resistant to damage from sunlight.
- 8. Liner will be 30-mil flexible PVC or 60-mil HDPE, string reinforced, impervious material, resistant to UV light, hydrocarbons, salt, acidic or basic liquids. The liner will have a hydraulic conductivity less than 1 x 10-9 cm/sec. Liner compatibility will comply with EPA SW-846.
- 9. The Mayre #1 below grade tank will be constructed with single walled sides and bottom which will be open for visual inspection for leaks. The below grade tank will be elevated a minimum of 6-inches above the underlying ground surface. The below grade tank will be underlain with a geo-membrane liner designed to divert any leaked fluid to a visual inspection point. Liner may be covered with gravel.
- 10. The Mayre #1 below grade tank will be equipped with a properly operating automatic high-level shut-off control device and manual controls to prevent overflows.
- 11. Diversionary berms, ditches or sloping will be constructed as necessary to prevent overflow and the collection of surface water entrapment.

Design Plan For Below Grade Tank



Dugan Production Corp.
Mayre #1

Mayre #1 Operational Requirements

The Mayre #1 below grade tank will be maintained and operated in accordance with the following requirements:

- 1. The Mayre #1 below grade tank will be operated and maintained to contain liquids and solids and maintain the integrity of the tank / liner system or secondary containment system to prevent contamination of fresh water and protect public health and environment.
- 2. All fluids will be recycled, reused, reclaimed or disposed of in a manner approved by NMOCD rules.
- 3. Do not dispose of solid waste, trash, debris or hazardous material into the pit.
- 4. If the Mayre #1 below grade tank develops a leak or if a penetration occurs below the liquids surface, all liquid will be removed above the damage or leak line within 48-hours. The NMOCD office will be notified within 48-hours of the discovery. The below grade tank / liner system or secondary containment system will then be either replaced or repaired.
- 5. Below grade tank will be constructed and operated in a manner that prevents the tank from over flow and prevents surface water from entering the pit. Diversion berms will be constructed around the sides of pit and an automatic high level shut-off will be installed.
- 6. Any measurable oil will be continuously removed from the Mayre #1 below grade tank to prevent a significant accumulation of oil overtime.
- 7. The Mayre #1 below grade tank will be inspected at least monthly and records of each inspection will be maintained for five years.
- 8. Adequate freeboard will be maintained to prevent overtopping of the Mayre #1 below grade tank.

Mayre #1 Closure Plan-Methods, Procedures and Protocols

1. Comply with deadlines for closure of a pit or below grade tank established by the State of New Mexico, Energy Minerals and Natural Resources Department 19.15.17.13 NMAC, or an earlier date if required by the NMOCD in the case of imminent danger to fresh water, public health or the environment.

Existing On June 16, 2008	Permit Applc. Submittal or Modification Request	File Closure Plan By	Stop Use By	Close By
Temporary Pit - Unlined	Not Permtd under 19 15.17	7/16/2008	Upon drlg rig release	9/16/2008
Permanent Pit - Unlined or Lined	Not permitted with NMOCD	7/16/2008	6-16-2008	12/16/2008
Permanent Pit - Unlined	Permitted or with NMOCD	12-16-2008	6-16-2010	6-16-2011
BGT-Aprvd. Design	Not Permtd under 19 15 17	12/16/2008	failed integrity replc	
	Apple by 9-16-2008		w/apprvd design	
BGTNot Aprval Design Nor Retrofts to Gomply Wals 15:177	Not Permtd under 19.15.17 Mod. Rqust by 9-16-2008	12/16/2008	6/16/2013	6-16-2013
BGT-Not Aprvd Design Nor Retrofit to comply w/19.15 17	NA	12/16/2008	6/16/2013	6/16/2013
Permanent Pit-Design and Constr	Mod Rqust by 12-16-2008	12/16/2008 submit w/mod	failed integrity replc	60-days after cessation
Does not comply w/19 15 17 permitted and lined	Comply w/in 18-mos of aprvl	request	w/apprvd design	
Permanent Pit-Design and Constr Does not comply w/19 15.17 Registered and Lined	Permit Apple by 12-16-2008 Comply w/in 18-mos of aprvl	12/16/2008 submit w/permit Applc		60-days after of cessation
Permanent Pit	Permitted under 19.15 17	60-Days prior to close		1
Temporary Pit	Permitted under 19.15.17	Prior to closure	Upon drlg rig release	6-mos after rig release
BGT	Permitted under 19.15.17	12/16/2013 or prior to closure	failed integrity replc w/apprvd design	60-days after cessation

- 2. The Mayre #1 below grade tank was registered under rule 50; however, it is not an approved design under rule 19.15.17. Upon approval of this application, the existing below grade tank will be closed and a new below grade tank that meets the design requirements of rule 19.15.17 will be constructed.
- 3. Below grade tank will be closed within 60-days after cessation of use.
- 4. Proof of closure notice will be provided by certified mail to surface owner after closure. Proof of notice will be attached to final closure report.

- 5. Remove all liquid from below grade tank prior to closure and dispose of at the Dugan Production operated Sanchez O'Brien #1 SWD (permit SWD-694) located 1650 feet from the South line and 990 feet from the West line (Unit L) of Section 6, Township 24 North, Range 9 West.
- 6. All solids from the below grade tank and all solids removed from the containment pit will be excavated, hauled to and disposed of at either the Envirotech facility (permit #NM-01-0011) facility located in Section 6, Township 26 North, Range 10 West or the IEI facility (permit NM-01-0010B) located in Section 2, Township 29 North, Range 12 West.
- 7. Remove below grade tank and dispose of in a NMOCD approved facility, or recycle, reuse, or reclaim it in a manner that the NMOCD approves.
- 8. On site equipment associated with the below grade tank will be removed unless it is needed for some other purpose.
- 9. Collect a five point, composite sample of the soils beneath the below grade tank (any area that is wet, discolored or shows evidence of a release) to demonstrate that Benzene, BTEX, TPH and chlorides do not exceed the standards as specified in 19.15.17.13.E or the background concentration, whichever is greater.

Components	Test Method	Limit (mg/kg)
Benzene	EPA SW-846 8021B or 8260B	0.2
BTEX	EPA SW-846 8021B or 8260B	50
TPH	EPA SW-846 418.1	100
GRO/DRO	EPA SW-846 8015M	NS
Chlorides	EPA 300.1	250 or Background

- 10. The NMOCD will be notified of the testing results on form C-141.
- 11. If it is determined that a release has occurred, rule 19.15.3.116 NMAC and 19.15.1.19 NMAC will be complied with as required.
- 12. If the sampling results demonstrate that a release has not occurred, or that any release does not exceed the concentrations specified above or background concentrations, the pit will be backfilled with compacted, non-waste containing, earthen material.
- 13. Stockpiled sub-surface soil will be used to backfill pit and re-contour (to a final or intermediate cover that blends with the surrounding topography). A minimum of four feet of compacted, non-waste containing, earthen material will be used as backfill.
- 14. Stockpiled surface soil will be used as a cover over the backfilled pit and disturbed area no longer needed for production operations. The soil cover will include either the background thickness of top soil or one foot of suitable material to establish vegetation at the site whichever is greater.
- 15. The area will be re-seeded as per BLM guidelines. Re-seeding will be repeated until 70% of the native natural cover is achieved and maintained for two successive growing seasons. The first growing season after the pit is closed the disturbed area will be re-seeded. The seeding method will be to drill on contour whenever possible.

- 16. The NMOCD will be notified within 60-days of closure of the below grade tank. The closure report will be filed on form C-144 and will document all closure activities, sampling results, a plot plan, and details on backfilling and capping where applicable.
- 17. The NMOCD will be notified once successful re-vegetation has been achieved.

Mayre #1 Request for Administrative Approval

Administrative approval is hereby requested for an alternative to the fencing design for the Mayre #1 below grade tank.

The request for administrative approval cited above is needed to help minimize environmental impact and increase safety and protect wildlife and public health. The alternative proposed will protect fresh water, public health, safety and the environment more effectively than the design and construction specifications established by the State of New Mexico, Energy Minerals and Natural Resources Department do in rule 19.15.17.11 NMAC.

1. The proposed alternative fencing design will include T-posts spaced 10-feet apart. Hog wire / field fence 4-feet in height will be strung tightly and anchored to the top and bottom of each T-post. Small holes (3" high X 6" wide) in the hog-wire will be located at ground level with increasing larger holes (up to 7" high X 6" wide) located at the top of the fence. Anchor braces will be put at all four corners to strengthen and tighten the fence. Two strands of barbed wire or a pipe / re-bar top rail will be constructed above the hog wire. This fence design (developed over the last 30-years) has proven to be very effective controlling unauthorized access to below grade tanks.

The existing rule (19.15.17.11.D.3) would require the operator to fence the below grade tank with a four foot fence that has at least four strands of barbed wire evenly spaced in the interval between on foot and four feet above the ground level. The proposed fencing alternative would provide better security against unauthorized access to below grade tanks. The smaller holes in hog-wire (3" X 6" up to 7" X 6") is more effective at controlling unauthorized access by the public and wildlife than 4-strands of barbed wire spaced 12" apart.

The proposed fence around the below grade tank will be constructed and operated in a manner that prevents unauthorized access and shall maintain the fence in good condition to protect the public and wildlife.

The request for administrative approval cited above is needed to help minimize environmental impact, increase safety and protect wildlife and public health. The alternatives proposed will protect fresh water, public health, safety and the environment more effectively than the design and construction specifications established by the State of New Mexico, Energy Minerals and Natural Resources Department do in rule 19.15.17.11 NMAC.