submitted in lieu of Form 3160-5

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to make any department or agency of the United States any talse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECIMEN

AUG 1 5 2008

pureau of Land Management Farmington Field Office Sundry Notices and Reports on Wells 5. Lease Number NM-03187 If Indian, All. or Type of Well 6. **Tribe Name** GAS 7. **Unit Agreement Name** Name of Operator BURLINGTON ESOURCES OIL & GAS COMPANY LP Well Name & Number 8. Lambe 7S Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. API Well No. 30-045-34316 Location of Well, Footage, Sec., T, R, M Field and Pool 10. Unit C (NENW), 1285' FNL & 1905' FWL, Section 21, T31N, R10W, NMPM **Basin Fruitland Coal WC Fruitland Sand** 11. **County and State** San Juan Co., NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission **Type of Action** Change of Plans Notice of Intent Abandonment X Other - Completion detail report Recompletion **New Construction RCVD AUG 19'08** X Subsequent Report Plugging Non-Routine Fracturing OIL CONS. DIV. Water Shut off Casing Repair Final Abandonment Altering Casing Conversion to Injection DIST. 3 13. Describe Proposed or Completed Operations 5//27/08 RU WL & RIH w/3.75" gauge ring to 3066'. Ran GR/CL/Gamma Ray from 3066' to surface. Cement was circulated to Surface on the 4-1/2" casing. RD & released WL. 7/14/08 NU frac valve & PT valve and casing to 4100 #/15 min. Good test. Perforated FC interval @ .32" - 3 spf: 2872'-2876', 2880' 2882', 2888'-2892' = 30 holes. RU to frac. Pumped 56,222 gal 70Q 1% coalfrac XE/75 Quality w/29,082 # 20/40 Brady sand & 488.5 scf N2. RIH w/4-1/2" CFP & set @ 2830'. Perf'd FS @ 2 spf .32" holes - 2718' - 2722', 2726' - 2734', 2736' - 2742', 2758' - 2764' = 48 holes. Frac'd w/108,360 gal 75Q 1% Coalfrac XE/75 Quality w/43,643# 20/40 Brady sand & 975.1scf N2. RD perf & frac crews. RU to flowback. FB for 3 days. RU WL & ran gauge ring to 2650' & set CBP @ 2649'. RD WL 7/17/08. 7/24/08 MIRU Basic 1320. ND WH, NU BOP, PT-OK. RIH w/mill & tagged CBP @ 2640'. M/O CBP @ 2640 & CFP @ 2829'. C/O fill to PBTD @ 3068' w/air & mist. C/O for 4 days. 7/31/08 RIH w/72 jts 2-3/8", 4.7# J-55 tubing and landed @ 2887' w/SN @ 2886'. RD floor. ND BOP. NU WH. RD & released rig 7/31/08. 14. I hereby certify that the foregoing is true and correct. Patsy Clugston Title Regulatory Specialist Date 8/15/08. ACATTEUTUTEULTE (This space for Federal or State Office use) APPROVED BY Date AUG 18 2008