



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-25-08 Operator Burlington Tes API #30-0 45-29936
Property Name VasalyCom Well No. 2 Location: Unit 3 Section 22 Township 30 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 91 Intermediate 5 Casing 104 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min					<u>101</u>
10 min					<u>101</u>
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>WAA</u>	<u>/</u>
Nothing	<u>/</u>	
Gas		
Gas & Water		
Water		<u>RCVD AUG 25 '08</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Braden head had nothing when opened.
Intermediate blew down in 10 seconds

By Geoff Davis
Geoff Davis (MSO)
(Position)

Witness

Monica Kuehling

E-mail address _____