District I 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

# State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office. For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or
Proposed Alternative Method Permit or Closure Plan Application
faction: Permit of a nit, closed-loop system, below-grade tank, or proposed alternative n

Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method X Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request Please be advised that approval of this request does not relieve theoperator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances. Operator: Energen Resources OGRID #: 162928 . Address: 2010 Afton Place, Farmington, New Mexico 87401 Facility or well name: San Juan 30-4 Unit #39 API Number: \_\_\_3003922210 OCD Permit Number: U/L or Qtr/Qtr F Section 18 Township 30N Range 4W County: Rio Arriba . Center of Proposed Design: Latitude 36.8148 Longitude -107.29958 NAD: ☐1927 X 1983 Surface Owner: X Federal State Private Tribal Trust or Indian Allotment RCVD AUG 25 '08 **NIL CONS. DIV.** Pit: Subsection F or G of 19.15.17.11 NMAC DIST. 3 Temporary: Drilling Workover Permanent Emergency Cavitation P&A ☐ Lined ☐ Unlined Liner type: Thickness mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other \_\_\_\_\_ ☐ String-Reinforced Liner Seams: Welded Factory Other Volume: bbl Dimensions: L x W x D Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of Drying Pad Above Ground Steel Tanks Haul-off Bins Other ☐ Lined ☐ Unlined Liner type: Thickness mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other Liner Seams: Welded Factory Other X Below-grade tank: Subsection I of 19.15.17.11 NMAC Volume: 62 bbl Type of fluid: Produced Water . Tank Construction material: Steel ☐ Secondary containment with leak detection ☐ Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off

Alternative Method:

☐ Visible sidewalls and liner X Visible sidewalls only ☐ Other

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)		
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church)	hospital,	
Four foot height, four strands of barbed wire evenly spaced between one and four feet		
Alternate. Please specify		
7.		
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)		
☐ Screen ☐ Netting ☐ Other ☐ Monthly inspections (If netting or screening is not physically feasible)		
Monthly inspections (11 netting or screening is not physically reasible)		
s. Signs: Subsection C of 19.15.17.11 NMAC		
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers		
☐ Signed in compliance with 19.15.3.103 NMAC		
9.		
Administrative Approvals and Exceptions:  Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.		
Please check a box if one or more of the following is requested, if not leave blank:		
Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval.	office for	
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.		
10. Siting Critoria (regarding powritting): 10.15.17.10 NIMAC		
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptance.	otable source	
material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appro office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a	priate district pproval	
Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or		
above-grade tanks associated with a closed-loop system.	☐ Yes ☐ No	
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells		
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).	☐ Yes ☐ No	
- Topographic map; Visual inspection (certification) of the proposed site		
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	│	
(Applies to temporary, emergency, or cavitation pits and below-grade tanks)  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image		
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	☐ Yes ☐ No ☐ NA	
(Applies to permanent pits)  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image		
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock	☐ Yes ☐ No	
watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.  - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site		
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes ☐ No	
adopted pursuant to NMSA 1978, Section 3-27-3, as amended.  - Written confirmation or verification from the municipality; Written approval obtained from the municipality		
Within 500 feet of a wetland.		
- US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes No	
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No	
Within an unstable area.	☐ Yes ☐ No	
- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map		
Within a 100-year floodplain FEMA map	☐ Yes ☐ No	

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are
attached.  Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC  Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC  Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
☐ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC ☐ Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number: or Permit Number:
12.  Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9  Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC  Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC  Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC  Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number:(Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC  Climatological Factors Assessment  Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC  Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC  Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC  Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC  Quality Control/Quality Assurance Construction and Installation Plan  Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC  Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC  Nuisance or Hazardous Odors, including H <sub>2</sub> S, Prevention Plan  Emergency Response Plan  Oil Field Waste Stream Characterization  Monitoring and Inspection Plan  Erosion Control Plan  Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.19 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.  Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative  Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only)
<ul> <li>☐ On-site Closure Method (Only for temporary pits and closed-loop systems)</li> <li>☐ In-place Burial ☐ On-site Trench Burial</li> <li>☐ Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)</li> </ul>
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached.  Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)  Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19.15.17.13.1 Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment if facilities are required.	
Disposal Facility Name: Disposal Facility Permit Number:	
Disposal Facility Name:	
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future ser   Yes (If yes, please provide the information below)  No	
Required for impacted areas which will not be used for future service and operations:  Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC  Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	С
17. Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate dist considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justi demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	rict office or may be
Ground water is less than 50 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Ground water is more than 100 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).  - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.  - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.  - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 500 feet of a wetland.  - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area.  - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan by a check mark in the box, that the documents are attached.  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC  Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC  Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	.15.17.11 NMAC

Operator Application Certification:  I hereby certify that the information submitted with this application is true, accur	arate and complete to the best of my knowledge and belief.
Name (Print):	Title:
Signature:	Date:
e-mail address:	Telephone:
20.  OCD Approval: ☐ Permit Application (including closure plan) ☐ Closure P	Plan (only)  OCD Conditions (see attachment)
OCD Representative Signature: Band Sell	Approval Date: <u>8 - 27 - 08</u>
Title: Enviro Spec	OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection Instructions: Operators are required to obtain an approved closure plan prior The closure report is required to be submitted to the division within 60 days of section of the form until an approved closure plan has been obtained and the complete.	to implementing any closure activities and submitting the closure report.  the completion of the closure activities. Please do not complete this
	☐ Closure Completion Date: 7/31/08 .
22.  Closure Method:  X Waste Excavation and Removal  On-Site Closure Method  Alterna  If different from approved plan, please explain. NO EXCAVATION	
Closure Report Regarding Waste Removal Closure For Closed-loop Systems Instructions: Please indentify the facility or facilities for where the liquids, dri two facilities were utilized.  Disposal Facility Name: NO WASTE DISPOSAL NECESSARY  Disposal Facility Name:  Were the closed-loop system operations and associated activities performed on o  Yes (If yes, please demonstrate compliance to the items below) No  Required for impacted areas which will not be used for future service and operations.	Disposal Facility Permit Number:  Disposal Facility Permit Number:  Disposal Facility Permit Number:  or in areas that will not be used for future service and operations?
☐ Site Reclamation (Photo Documentation) ☐ Soil Backfilling and Cover Installation ☐ Re-vegetation Application Rates and Seeding Technique	
Closure Report Attachment Checklist: Instructions: Each of the following it mark in the box, that the documents are attached.  X Proof of Closure Notice (surface owner and division)  □ Proof of Deed Notice (required for on-site closure)  □ Plot Plan (for on-site closures and temporary pits)  X Confirmation Sampling Analytical Results (if applicable)  □ Waste Material Sampling Analytical Results (required for on-site closure)  □ Disposal Facility Name and Permit Number  □ Soil Backfilling and Cover Installation  □ Re-vegetation Application Rates and Seeding Technique  □ Site Reclamation (Photo Documentation)  On-site Closure Location: Latitude Longi	•
25.	
Operator Closure Certification:  I hereby certify that the information and attachments submitted with this closure belief. I also certify that the closure complies with all applicable closure requires	
Name (Print): Ed Hasely	Title: Sr. Environmental Engineer .
Signature: 2 Hasely	Date: 8/21/08
e-mail address: ed.hasely@energen.com	Telephone: (505) 324-4131

# BELOW-GRADE TANK CLOSURE REPORT

### **ENERGEN RESOURCES**

#### San Juan 30-4 Unit #39

### **CLOSURE STEPS:**

- (1) Notified the surface owner (Forest Service) by certified mail, return receipt requested, of the plans to close the below-grade tank. ---- <u>Letter Attached</u>
- (2) Notified the Aztec OCD office (Brandon Powell 334-6178, Ext 15) verbally and by Email prior to the planned closure operation. ---- Email Attached
- (3) The tank contained no liquids at the time of the work.
- (4) Removed the below-grade tank for re-use in an above-ground setup.
- (5) Tested the soils beneath the below-grade tank to determine whether a release has occurred.
  - Collected a five point, composite sample;

Analyzed for BTEX, TPH and chlorides: ---- Analyses Attached

- Benzene concentration ND
- Total BTEX concentration 0.0125 ppm
- TPH concentration 500 ppm (exceedance of determining a release)
- Chloride concentration 36 ppm
- (6) The soil analyses showed that the soils exceeded the TPH concentration (418.1 method) specified in 19.15.17 NMAC as an indication of a release. Remediated per 19.15.3.116 NMAC.
- (7) Backfilled the excavation with compacted, non-waste containing, earthen material in a manner that will prevent ponding or erosion.
- (8) The area is needed for operations as the tank will be set above ground in the same location. Seeding and final reclamation will take place upon P&A.

### **FINAL CLOSURE REPORT:**

Submitted a closure report on form C-144, with necessary attachments to document all closure activities including sampling results, within 60 days of closure completion.



# EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Energen	Project #:	03022-0001
Sample ID:	Pit Sample	Date Reported:	08-06-08
Laboratory Number:	46570	Date Sampled:	07-31-08
Chain of Custody:	4922	Date Received:	07-31-08
Sample Matrix:	Soil	Date Analyzed:	08-05-08
Preservative:		Date Extracted:	08-04-08
Condition:	Plastic Bottle	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	t	
_				
Benzene	ND	0.9		
Toluene	5.2	1.0		
Ethylbenzene	1.0	1.0		
p,m-Xylene	2.5	1.2		
o-Xylene	3.8	0.9		
Total BTEX	12.5			

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	ter Percent Recovery	
	Fluorobenzene	97.0 %	
	1,4-difluorobenzene	97.0 %	
	Bromochlorobenzene	97.0 %	

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

San Juan 30-4 #39

Analyst

Christian Walters
Review



# EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	Energen	Project #:	03022-0001
Sample ID:	Pit Sample	Date Reported:	08-04 <b>-</b> 08
Laboratory Number:	46570	Date Sampled:	07-31-08
Chain of Custody No:	4922	Date Received:	07-31-08
Sample Matrix:	Soil	Date Extracted:	08-01-08
Preservative:		Date Analyzed:	08-01-08
Condition:	Plastic Bottle	Analysis Needed: ,	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

**Total Petroleum Hydrocarbons** 

500

5.0

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

San Juan 30-4 #39.

Analyst



### Chloride

Client: Sample ID: Lab ID#:

Energen
Pit Sample
46570

Project #:
Date Reported:
Date Sampled:

03022-0001 08-04-08 07-31-08 07-31-08

Sample Matrix: Preservative:

Soil

Date Received: Date Analyzed:

08-04-08

Condition:

Plastic Bottle

Chain of Custody:

4922

**Parameter** 

Concentration (mg/Kg)

**Total Chloride** 

36.0

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

San Juan 30-4 #39.

Analyst

/ Mistle m Westers
Review



July 30, 2008

Certified Mail: 0002 5579 5474

Jicarilla Ranger District **US Forest Service** 664 East Broadway Bloomfield, New Mexico 87413 Attn: Mr. Mark Catron

Re:

Below Grade Tank Closure San Juan 30-4 Unit #39

Dear Mr. Catron:

As stated in an E-mail to Mr. Mark Catron on July 30, 2008, Energen Resources plans to close a below grade tank located on the subject well location. New Mexico Oil Conservation Division rules and guidelines will be followed. The well is located in Unit Letter F, Section 18, Township 30N, Range 4W in Rio Arriba County, New Mexico.

If there are any questions or concerns, please contact me at 505-330-3584.

(Transfer from service label)

Energen Resources Corporation, an Et PS Form 3811, February 2004

Sincerely. U.S. Postal Service. stic Mail Only; No Insurance Coverage Prov Ed Hasely Sr. Environmental Engineer 579 **Energen Resources** 30-4 # 39 BGT COMPLETE THIS SECTION ON DELIVERY SENDER: COMPLETE THIS SECTION ■ Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. C. Date of Delivery Attach this card to the back of the mailpiece, Cc: Well File or on the front if space permits. Correspondence D. Is delivery address different from item 1? 1. Article Addressed to: If YES, enter delivery address below: Jicarilla Ranger District 664 E. Broadway Blenfield NM 87413 3. Service Type Certified Mail ☐ Express Mail Alli Mark Cation □ Registered ☐ Return Receipt for Merchandis ☐ Insured Mail C.O.D. 4. Restricted Delivery? (Extra Fee) ☐ Yes F:\Below Grade Tanks\Forest Servi 2. Article Number

7007 2680 0002 5579 5474

102595-02-M-15

Domestic Return Receipt

# **Ed Hasely**

From: Ed Hasely

Sent: Wednesday, July 30, 2008 3:42 PM

To: 'Powell, Brandon, EMNRD'

Cc: Sam Mohler

Subject: BGT Closure - San Juan 30-4 Unit #39

Brandon - Due to a drilling rig moving onto our existing San Juan 30-4 Unit #39 location, we need to remove (close) a below-grade tank tomorrow (7/31). Due to the urgency, I have asked for sample(s) to be collected from beneath the tank as per the Pit Rule (5-point composite + samples of any wet or visibly impacted soils) and the hole backfilled to allow the rig to move in. The exact location of the BGT will be marked in case further action is necessary. I have notified the landowner (Forest Service) by email and certified mail of our intentions to close the BGT.

I sent you a DRAFT BGT Closure Plan back on 7/18, but have not heard back from you on it. Please let me know your comments on the draft plan so I can finalize and submit all the C-144s / closure plans. That way we will not run into these "emergencies". Thanks.

### **Ed Hasely**

**Energen Resources Corporation** 

Sr. Environmental Engineer ed.hasely@energen.com
Office: (505) 324-4131
Cell: (505) 330-3584