



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-3-08 Operator Gene Furlong Inc. API #30-0 45 21672
Property Name Rundemon Well No. 2 Location: Unit B Section 26 Township 31 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 111 Intermediate 111 Casing 111 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min			111		
10 min			111		
15 min			118		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges


Down to Nothing

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 111

REMARKS:

Slim hole - Blew head 5 seconds - soft
for 15 seconds then nothing
Has house top

By Brad Furlong

Witness Monica Furlong

(Position)

E-mail address _____