



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-5-08 Operator Burlington API #30-0 15 ¹⁰³⁴¹
Property Name Burlington Well No. 1 Location: Unit A Section 25 Township 3 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 203 Intermediate 0 Casing 226 Bradenhead 32

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		0	227		
10 min		0	227		
15 min		0	227		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	RCVD SEP 5 '08
Gas	OIL CONS. DIV.
Gas & Water	DIST. 3
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Blew down in 8 seconds
intermediate had a whisp when opened.

By Bradon Ferra

Witness Monica Fuchling

(Position)

E-mail address _____