



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9-4-08 Operator Benson Monica Giron API # 30-0 39-22592

Property Name El Puerto Chig. Man Well # 40 Location: Unit E Sec 19 Twn 27 Rge 1E

Land Type:

State _____
Federal _____
Private _____
Indian ☒

Well Type:

Water Injection ☒
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N TA Expires: _____

Casing Pres. 90
Bradenhead Pres. 0
Tubing Pres. Vacuum
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

RCVD SEP 4 '08
OIL CONS. DIV.
DIST. 3

Pressured annulus up to 380 psi. for 30 mins. Test passed/failed

REMARKS:

Packer set at 3187'
top perf 3260'

By Ben L. Longley
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

(Position)

Revised 02-11-02

86

