

UNITED STATES
DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
TO DRILL" for permit for such proposals

Use "APPLICATION

Bureau of Land Management
Farmington Field Office

Lease Designation and Serial No.
NMSF-078889

If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE		7	If Unit or CA, Agreement Designation Rosa Unit
1.	Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	8	Well Name and No. #380
2.	Name of Operator WILLIAMS PRODUCTION COMPANY, LLC	9	API Well No. 30-039-27491
3.	Address and Telephone No. PO BOX 640, AZTEC, NM 87410 (505) 634-4200	10	Field and Pool, or Exploratory Area Basin Fruitland Coal
4.	Location of Well (Footage, Sec., T., R, M, or Survey Description) 2600' FSL & 750' FWL, SEC 20, T31N, R4W	11.	County or Parish, State Rio Arriba, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	Abandonment
<input type="checkbox"/> Subsequent Report	Recompletion
<input type="checkbox"/> Final Abandonment	Plugging Back
	Casing Repair
	Altering Casing
	SURFACE CASING
	Other
	Change of Plans
	New Construction
	Non-Routine Fracturing
	Water Shut-Off
	Conversion to Injection
	Dispose Water
	(Note. Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9/18/08

TD- 12 1/4" SURF HOLE @ 350', 0530 HRS

RCVD SEP 29 '08

OIL CONS. DIV.

DIST. 3

9/19/08

RAN 7 JTS, 9 5/8', 36#, K-55, 8rD - ST&C, CSG SET @ 341', FC @ 293'

CEMENT 9-5/8" CASING @ 341.32' - SHOE DEPTH / SINGLE SLURRY CEMENT JOB / 20 BBLs. FRESH WATER SPACER / 150 SXS TYPE 3 CEMENT + 2% CaCl-2 + .25#/SX CELLO FLAKE + 24.42 BBL. WATER = 80.62 BBL. (212 CuFt) SLURRY @ 14.5 PPG (YIELD = 1.41 / WGPs = 6.84) / DISPLACE WITH 22.9 BBL. WATER / 1200PSI, PLUG DOWN ON 9/19/08, @ 1337 HRS 200 PSI SHUT IN, 10 BBLs. OF CEMENT RETURNS TO SURFACE. ✓

INSTALL TEST PLUG & TEST BOP PIPE & BLIND RAMS, CHOKE MANIFOLD VALVES, MUD CROSS VALVES, FLOOR VALVE KELLY @ 250# 5-MIN EACH & 1500# 10-MIN EACH. TEST 9 5/8" CSG @ 1500# 30-MIN. TEST PUMP & TEST CHARTS USED ON ALL TEST. ALL TESTED GOOD. ✓

14 I hereby certify that the foregoing is true and correct

Signed

Larry Higgins

Title Drilling COM

Date 9/22/08

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any

RECEIVED FOR RECORDS

SEP 26 2008

FARMINGTON FIELD OFFICE

BY T. Salazar