

Bill Richardson Governor

Joanna Prukop Cabinet Secretary Reese Fullerton Deputy Cabinet Secretary Mark Fesmire Division Director Oil Conservation Division



October 7, 2008

Sharon Zubrod Burlington Resources Oil and Gas Company PO Box 4289 Farmington NM 87499

Re: Howell C 3, B, 7, 30N, 8W, API # 30-045-12139

Dear Ms. Zubrod:

The 2008 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before January 9, 2009. Initial Bradenhead psi of 101 was reported with a 5 minute shut in pressure of 47 psi.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement tops, and provide gas analysis from all casing strings.

Reference: RBDMS KGR0828162524 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly G. Roberts Deputy Oil and Gas Inspector District III - Aztec

CC: Well File