

# BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 17th 2008 Operator Thompson E & P API #30-0 45-07730  
Property Name Hartman Well No. #2 Location: Uni A Section 31 Township 29 N Range 11 W  
Pressure (Shut-In or Producing) Producing Tubing 4 Intermediate NA Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	0	NA	6	Steady Flow		
10 minutes	0	NA	6	Surges		
15 minutes	0	NA	6	Down to Nothing		
20 minutes	0	NA	6	Nothing	Nothing	
25 minutes	0	NA	6	Gas		
30 minutes	0	NA	6	Gas & Water		
				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR        FRESH        SALTY        SULFUR        BLACK       

5 MINUTE SHUT-IN        0 BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

1 " ball valve was frozen shut, Very small ammount of pressure (TSTM) for less than 1 second then nothing. Replaced bad valve

By George H Reid Witness         
Contract pumper  
(Position)

