



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

30-045-08113

Date of Test August 19-08 Operator Paula Stone OKG (131924) API #30-0Property Name Bunce Fed. Com Well No. #100 Location: Unit NE Section 19 Township 29N Range 10WWell Status (Shut-In or Producing) Initial PSI: Tubing 151 Intermediate NE Casing 318 Bradenhead 1.3 Psig

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	151	318		
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

RCVD NOV 7 '08

OIL CONS. DIV.

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

MINUTE SHUT-IN PRESSURE

BRADENHEAD

0 Psig

INTERMEDIATE

REMARKS:

Bradenhead Blew down to 0 Psig in a Puff. No flow.
1st Blew down Valve.Willard Hottell

Witness

970. 759-8703 CONTRACTOR
(Position)Oil address CH MLDR @ CHEVRON.COM