



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6178
[http://emurcd.state.nm.us/ocd/District 3/district.htm](http://emurcd.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 8/19/08 Operator Four Star OIL API #30-0 45-21537
(131994)
Property Name New Mexico Com A Well No. 2 Location: Unit SW/SE Section 32 Township 29N Range 10W
Well Status (Shut-In or Producing) Tubing 12 Intermediate 12 Casing 12 Bradenhead NO

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>12</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	RCVD NOV 7 '08
30 minutes			Gas & Water	OIL CONS. DIV.
			Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD NO INTERMEDIATE _____

REMARKS:

This is a slim hole. No Bradenhead.
Dug To Check.

By William Hattell
CONTRACTOR
(Position)

Witness _____

MLDR ECHUROW. COM