



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6178
[http://emrwd.state.nm.us/ocd/District 3/district.htm](http://emrwd.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 8/19/08 Operator Four Star O&G (131994) API #30-0 45-30664
Property Name New Mexico State 36 Well No. 36-2 Location: Unit NE/NE Section 36 Township 30N Range 10W
Well Status (Shut-In or Producing) Tubing 63 Intermediate Casing 63 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>Tubing 63</u>	<u>63</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing <u>0 Psig</u>	
25 minutes			Gas	<u>RCVD NOV 7 '08</u>
30 minutes			Gas & Water	<u>OIL CONS. DIV.</u>
			Water	<u>DIST. 3</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS: Found 0 Psig No Flow. Pump Jack Down.

By Richard Hottel
CONTRACTOR
(Position)

Witness

MLDR @ CHEVRON.COM