



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-21-09 Operator Dugan Prod. API #30-0 45-22295
Property Name Leopore SWB Well No. 1 Location: Unit M Section 17 Township 25 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 16 1/2" plug Intermediate N/A Casing 20 Bradenhead 17

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min			20		
10 min			20		
15 min			20		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	RCVD JAN 21 '09
Nothing	OIL CONS. DIV.
Gas	DIST. 3
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

opened through 1/4" valve - blew to nothing in 3 min.

By Ray Callison

Witness

Monica Kuehling

(Position)

E-mail address _____